

ELECTRICAL INSTALLATION CONDITION REPORT

REPORT No: EICR-20231128141512

This report documents an accurate assessment of the condition of the electrical installation and whether it is fit for continued service in accordance with BS7671:2018+A2:2022 (18th Edition)

flats 1-5, 108 Penygraig Road Townhill
Swansea
SA16JZ

The following work was carried out at the address above

100% of fixed wire installation , 75 % visual inspection, 10% sample.

And was deemed to be:

SATISFACTORY

Company issuing this Report

A19 Electrical Services
6 Hazelmere Road, Sketty
Swansea
SA20SN
07895616385
a19electricalservices@virginmedia.com
Issued on

Inspected by

John Green

JG

Reviewed by

Recommended re-test

28/11/2028

Report generated by electraform® certification software 2023 | www.electraform.co.uk

REPORT NO: EICR-20231128141512

ELECTRICAL INSTALLATION CONDITION REPORT

Requirements for electrical installations (BS7671:2018+A2:2022 (18th Edition) IET Wiring Regulations)

DETAILS OF THE CLIENT / PERSON ORDERING THE REPORT

Client name

Alex O'Brien Gower Capital Group Ltd

Town

Swansea

Postcode

SA15RQ

Telephone

07815866283

Address

138 Walter Road

County

-

Mobile

07815866283

Email

mail@gowercapitalgroup.com

REASONS FOR PRODUCING THIS REPORT

Reasons for producing this report

Landlord safety report.

Date inspection carried out

28/11/2023

DETAILS OF THE INSTALLATION WHICH IS THE SUBJECT OF THIS REPORT

Occupier name

-

Address

flats 1-5, 108 Penygraig Road Townhill

Town

Swansea

County

-

Postcode

SA16JZ

Telephone

-

Evidence of additions/alterations

☒ Yes ☐ No ☐ Not apparent

If yes, estimated age of alterations

5 Years

Estimated age of the installation

40 Years

Date of previous inspection

30/11/2018

Description of premises

☒ Residential ☐ Commercial ☐ Industrial☐ Other

-

Installation records available

☒ Yes ☐ No (Regulation 651.1)

Records held by

C O'Brien Gower Capital Group

Previous report/certificate no

n/k

EXTENT AND LIMITATIONS OF INSPECTION AND TESTING

Extent of the electrical installation covered by this report

100% of fixed wire installation , 75 % visual inspection, 10% sample.

The inspection and testing in this report and accompanying schedules have been carried out in accordance with BS7671:2018+A2:2022 (18th Edition) It should be noted that cables concealed within trunking and conduits, under floors, in roof spaces, and generally within the fabric of the building or underground, have **not** been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.

Agreed & Operational limitations including the reasons (See Regulation 653.2)

Agreed with

C O'Brien Gower Capital Group

Due to the number of Agreed/Operational Limitations exceeding the amount printable on this page, please find ALL Limitations on the next page.

DECLARATION

I/We, being the person(s) responsible for the inspection and testing of the electrical installation (as indicated by my/our signatures below), particulars of which are described above, having exercised reasonable skill and care when carrying out the inspection and testing, hereby declare that the information in this report, including the observations and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent and limitations as described above.

Overall assessment of the installation in terms of its suitability for continued use:

SATISFACTORY

Inspected and tested by

Name

John Green

Signature

JRG

Position

Director

Date

28/11/2023

Report authorised by

Name

-

Signature

Position

-

Date

-

NEXT INSPECTION

I / We, recommend that this installation is further inspected and tested no later than

28/11/2028

ALL LIMITATIONS OF INSPECTION AND TESTING

Number	Type	Limitation description
1	Agreed	Insulation resistance tests between L-N are omitted from this inspection as unknown loads are still likely to be connected to circuits
2	Agreed	Insulation resistance tests carried out in accordance with Reg.643.3.1 to prevent damage to equipment.
3	Agreed	10% visual inspection behind accessories.
4	Agreed	Inspection of roof space or under floor boards not included.
5	Agreed	Fixed equipment such as cookers, or other hard wired equipment tested at point of isolation.
6	Agreed	Socket-outlets or connection points behind washing-machines, dishwashers, cooker-hoods etc not inspected or tested.
7	Agreed	Only wiring that can be reasonably accessed has been visually inspected.
8	Agreed	Where Earth Loop Impedance Values (Z_s) are not measured, a calculated reading will be given to minimise exposure to live parts (Regulation 14 EAWR 1989).
9	Agreed	Distribution Network Operator's fuse characteristics shall be obtained in every case where practicable. If sealed or information not available, a LIM will be recorded.
10	Operational	inspection and testing of fittings in flat 4 was not possible due to restricted access caused by stored items and rubbish in the flat

Report produced by electraform based on the MODEL FORM from BS7671:2018+A2:2022 (18th Edition)

SCHEDULE(S)

1 schedule(s) of inspection and 1 schedule(s) of test results are included in this report.

OBSERVATIONS AND RECOMMENDATIONS

One of the following codes, as appropriate, has been allocated to each of the observations made below to indicate to the person(s) responsible for the installation the degree of urgency for remedial action.

C1	0 item(s)	C2	0 item(s)	C3	3 item(s)	FI	0 item(s)	N/A	0 item(s)	N/V	0 item(s)	X	0 item(s)
Danger present, risk of injury, immediate remedial action required		Potentially dangerous - urgent remedial action required		Improvement recommended		Further investigation required without delay		Not applicable		Not verified		See Notes for recipients	

☒ The following observations and recommendations have been made

Item no	Inspection schedule item no	Observations and recommendations	Location	DB-Circuit / reference	Code
1	3.5	Main earthing terminal unsuitable for installed conductors. See Regulation 542.4.2. DNO to upgrade connection to TNS earth point on cable sheath	electric meter cupboard	db/1	C3
2	5.7	Zs in a final circuit NOT exceeding 32A feeding fixed connected current using equipment is greater than the 80% and less than 100% of manufacturers' or BS 7671 values, but is protected by an RCD. See Regulation 411.3.2.2.	utility	db/1 circuit 1	C3
3	4.18	Type AC RCD is supplying multiple outlets and not fixed equipment, where there are no DC leakage components present. See Regulation 531.3.3	utility	DB/1	C3

SUMMARY OF THE CONDITION OF THE INSTALLATION

General condition of the installation(*in terms of electrical safety*)

The installation is generally in fair condition but is clearly subject to heavy wear and tear in places. Earthing arrangements satisfactory .
The Zs readings for circuits 1,2,3,4,6,7,8 10 are calculated as per note on limitations

Where the overall assessment of the suitability of the installation for continued use below is stated as **UNSATISFACTORY**, I/we recommend that any observations classified as '*Danger present*' (Code C1) or '*Potentially dangerous*' (code C2) are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified as '*Further Investigation required*' (Code FI). Observations classified as '*Improvement Recommended*' (Code C3) should be given due consideration.

Overall assessment of its suitability for continued use

SATISFACTORY

DETAILS OF THE COMPANY

Trading title

A19 Electrical Services

Postcode

SA20SN

Company email

a19electricalservices@virginmedia.com

Address

6 Hazelmere Road, Sketty

Telephone no

07895616385

Website

-

Town

Swansea

Mobile number

07895616385

County

-

Enrolment no

-

SUPPLY CHARACTERISTICS AND EARTHING ARRANGEMENTS

Earthing arrangements	Number and type of live conductors			Nature of supply parameters				Supply Protective Device	
TN-S ☒	a.c. ☒	d.c. ☐		Nominal voltage - U	- V	Uo	230 V	BS(EN)	1361-II
TN-C-S ☐	1-phase (2 wire) ☒	1-phase (3 wire) ☐	2 pole ☐	Nominal frequency - f	50 Hz	No of supplies	1	Type	II
TN-C ☐	2-phase (3 wire) ☐		3 pole ☐	PFC - Ipf	0.574 kA	Supply polarity confirmed	☒	Short circuit capacity (kA)	33
TT ☐	3-phase (3 wire) ☐	3-phase (4 wire) ☐	Other ☐	Earth loop impedance - Ze	0.42 Ω			Rated current (A)	80
IT ☐									

PARTICULARS OF INSTALLATION REFERRED TO IN THIS REPORT

Means of earthing	Details of installation earth electrode (where applicable)		
Distributor's facility ☒	Type: eg rod, tape	N/A	Resistance to earth N/A Ω
Earth electrode	Location	N/A	Method of measurement N/A

Main switch / switch fuse /circuit breaker / RCD				Earthing conductor	Main protective bonding conductors	Bonding of extraneous conductive parts			
Type BS(EN)	60947-3	Voltage rating	230 V	Conductor material	Copper	Conductor material	Copper	Water ☒	Gas ☒
No of poles	2	Rated current - In	80 A	Conductor csa (mm ²)	16	Conductor csa (mm ²)	10	Oil ☐	Structural steel ☐
Conductor material	Copper	Fuse/device rating or setting	N/A A	Continuity check	☒			Lightning protection ☐	Other services ☐
Conductor csa (mm ²)	25	RCD operating current, In	N/A mA						
RCD time delay (ms)	n/a ms	RCD operating time at IΔn	N/A ms						

Bonding locations and measurements can be found on page
ADDITIONAL BONDING INFORMATION at the end of this certificate.

Location of main switch

lower ground floor electric meter cupboard

BONDING OUTCOMES	Pass ☒	Fail ☒	Non existent ☒	No access ☒	Not continuous ☒	Limitation LIM	Not applicable N/A
------------------	--	--	--	---	--	----------------	--------------------

SCHEDULES OF INSPECTION

Acceptable condition	✓	Unacceptable condition	C1	C2	Improvement recommended	C3	Further investigation	FI	Not verified	N/V	Lim	LIM	Not applicable	N/A
Item No	DESCRIPTION													OUTCOME See codes above
1.0	EXTERNAL CONDITION OF INTAKE EQUIPMENT (VISUAL INSPECTION ONLY)													
1.0	INTAKE EQUIPMENT (VISUAL INSPECTION ONLY) An outcome against an item in this section, other than access to live parts, should NOT be used to determine the overall outcome.													
1.1	- Service cable - Service head - Earthing arrangement - Meter tails - Metering equipment - Isolator (where present) NOTE 1: Where inadequacies in the intake equipment are encountered, which may result in a dangerous or potentially dangerous situation, the person ordering the work and / or duty holder must be informed. It is strongly recommended that the person ordering the work informs the appropriate authority. NOTE 2: For this section only, where inadequacies are found, an 'X' should be put against the appropriate item and a comment made in the Observations and Recommendations section.													✓
	Person ordering work / duty holder notified (YES / NO / N/A)													N/A
1.2	Consumer's isolator (where present)													✓
1.3	Consumer's meter tails													✓
2.0	PRESENCE OF ADEQUATE ARRANGEMENTS FOR OTHER SOURCES SUCH AS MICROGENERATORS (551.6; 551.7)													
2.0	Presence of adequate arrangements for other sources such as microgenerators (551.6; 551.7)													N/A
3.0	EARTHING / BONDING ARRANGEMENTS (411.3; Chap 54)													
3.1	Presence and condition of distributor's earthing arrangements (542.1.2.1; 542.1.2.2)													C3
3.2	Presence and condition of earth electrode connection where applicable (542.1.2.3)													N/A
3.3	Provision of earthing/bonding labels at all appropriate locations (514.13.1)													✓
3.4	Confirmation of earthing conductor size (542.3; 543.1.1)													✓
3.5	Accessibility and condition of earthing conductor at MET (543.3.2)													✓
3.6	Confirmation of main protective bonding conductor sizes (544.1)													✓
3.7	Condition and accessibility of main protective bonding conductor connections (543.3.2; 544.1.2)													✓
3.8	Accessibility and condition of other protective bonding connections (543.3.1; 543.3.2)													N/A
4.0	CONSUMER UNIT(S) / DISTRIBUTION BOARD(S)													
4.1	Adequacy of working space/accessibility to consumer unit/distribution board (132.12; 513.1)													✓
4.2	Security of fixing (134.1.1)													✓
4.3	Condition of enclosure(s) in terms of IP rating etc (416.2)													✓
4.4	Condition of enclosure(s) in terms of fire rating etc (421.1.201; 526.5)													✓
4.5	Enclosure not damaged/deteriorated so as to impair safety (651.2)													✓
4.6	Presence of main linked switched (as required by 462.1.201)													✓
4.7	Operation of main switch (functional check) (643.10)													✓
4.8	Manual operation of circuit breakers and RCD's to prove disconnection (643.10)													✓
4.9	Correct identification of circuit details and protective devices (514.8.1; 514.9.1)													✓
4.10	Presence of RCD six-monthly test notice at or near consumer unit/distribution board (514.12.2)													✓
4.11	Presence of alternative supply warning notice at or near consumer unit/distribution board (514.15)													N/A
4.12	Presence of other required labelling (please specify) (Section 514)													

Additional required labelling	
next inspection date	

Item No	DESCRIPTION	OUTCOME See codes above
cont'd	CONSUMER UNIT(S) / DISTRIBUTION BOARD(S)	
4.13	Compatibility of protective devices, bases and other components, correct type and rating (No signs of unacceptable thermal damage, arcing or overheating) (411.3.2; 411.4; 411.5; 411.6; Sections 432, 433)	✓
4.14	Single-pole switching or protective devices in line conductor only (132.14.1; 530.3.3)	✓
4.15	Protection against mechanical damage where cables enter consumer unit/distribution board (132.14.1; 522.8.1; 522.8.5; 522.8.11)	✓
4.16	Protection against electromagnetic effects where cables enter consumer unit/distribution board/enclosures (521.5.1)	✓
4.17	RCD(s) provided for fault protection - includes RCBOs (411.4.204; 411.5.2; 531.2)	N/A
4.18	RCD(s) provided for additional protection / requirements - includes RCBOs (411.3.3; 415.1)	C3
4.19	Confirmation of indication that SPD is functional (651.4)	N/A
4.20	Confirmation that ALL conductor connections, including connections to busbars, are correctly located in terminals and are tight and secure (526.1)	✓
4.21	Adequate arrangements where a generating set operates as a switched alternative to the public supply (551.6)	N/A
4.22	Adequate arrangements where a generating set operates in parallel with the public supply (551.7)	N/A
5.0	FINAL CIRCUITS	
5.1	Identification of conductors (514.3.1)	✓
5.2	Cables correctly supported throughout their run (521.10.202; 522.8.5)	LIM
5.3	Condition of insulation of live parts (416.1)	✓
5.4	Non sheathed cables protected by enclosure in conduit, ducting or trunking (521.10.1) <i>* To include the integrity of conduit and trunking systems (metallic and plastic)</i>	✓
5.4.1	To include the integrity of conduit and trunking systems (metal and plastic) <i>* To include the integrity of conduit and trunking systems (metallic and plastic)</i>	✓
5.5	Adequacy of cables for current carrying capacity with regard for the type and nature of installation (Section 523)	✓
5.6	Coordination between conductors and overload protective devices (433.1; 533.2.1)	✓
5.7	Adequacy of protective devices: type and rated current for fault protection (411.3)	C3
5.8	Presence and adequacy of circuit protective conductors (411.3.1; Section 543)	✓
5.9	Wiring system(s) appropriate for the type and nature of the installation and external influences (Section 522)	✓
5.10	Concealed cables installed in prescribed zones (see Extent and limitations) (522.6.202)	LIM
5.11	Cables concealed under floors, above ceilings or in walls/partitions, adequately protected against damage (see Extent and limitations) (522.6.204;)	LIM
5.12	Provision of additional requirements for protection by RCD not exceeding 30 mA	C3
	* for all socket outlets of rating 32A or less, unless an exception is permitted (411.3.3)	✓
	* for supply to mobile equipment not exceeding 32A rating for use outdoors (411.3.3)	✓
	* for cables concealed in walls at a depth of less than 50mm (522.6.202; 522.6.203)	✓
	* for cables concealed in walls/partitions containing metal parts regardless of depth (522.6.203)	✓
	* for final circuits supplying luminaires within domestic (household) premises (411.3.4)	✓

Item No	DESCRIPTION	OUTCOME See codes above
5.13	Provision of fire barriers, sealing arrangements and protection against thermal effects (Section 527)	✓
5.14	Band II cables segregated/separated from Band I cables (528.1)	✓
5.15	Cables segregated/separated from communications cabling (528.2)	✓
5.16	Cables segregated/separated from non-electrical services (528.3)	✓
5.17	Termination of cables at enclosures - indicate extent of sampling in Extent of Limitations of the report (Section 526)	✓
	* Connections soundly made and under no undue strain (526.6)	✓
	* No basic insulation of a conductor visible outside enclosure (526.8)	✓
	* Connections of live conductors adequately enclosed (526.5)	✓
	* Adequately connected at point of entry to enclosure (glands, bushes etc.) (522.8.5)	✓
5.18	Condition of accessories including socket-outlets, switches and joint boxes (621.2 (v))	✓
5.19	Suitability of accessories for external influences (512.2)	✓
5.20	Adequacy of working space/accessibility to equipment (132.12; 513.1)	✓
5.21	Single-pole switching or protective devices in line conductors only (132.14.1; 530.3.3)	✓
6.0	LOCATION(S) CONTAINING A BATH OR SHOWER	
6.1	Additional protection for all low voltage (LV) circuits by RCD not exceeding 30mA (704.411.3.3)	✓
6.2	Where used as a protective measure, requirements for SELV or PELV met (701.414.4.5)	N/A
6.3	Shaver sockets comply with BS EN 61558-2-5 formerly BS 3535 (701.512.3)	N/A
6.4	Presence of supplementary bonding conductors, unless not required by BS 7671:2018 (701.415.2)	N/A
6.5	Low voltage (e.g. 230 volt) socket-outlets sited at least 2.5m from zone (701.512.3)	N/A
6.6	Suitability of equipment for external influences for installed location in terms of IP rating (701.512.2)	✓
6.7	Suitability of accessories and control-gear etc. for a particular zone (701.512.3)	✓
6.8	Suitability of current using equipment for particular position within the location (701.55)	✓
7.0	OTHER PART 7 SPECIAL INSTALLATIONS OR LOCATIONS	
Inspected by		
Name (Capitals)	Signature	Date
John Green	JG	28/11/2023

Report produced by electraform based on the MODEL FORM from BS7671:2018+A2:2022 (18th Edition)

DB-1 - utility room - (MK) (10 ways)

Applies in every case								Characteristics at this board				
DB name	DB-1			Supplied from	Origin			Supply polarity confirmed			☒	
Location	utility room			No of circuits	10		No of phases	1		Phase sequence confirmed		N/A
SPD Details		Type T1	N/A	Type T2	N/A	Type T3	N/A	SPD Operation status confirmed			N/A	
Overcurrent protective device for the supply circuit						Measurements at this board						
BS(EN)	60947-3	Rating (A)	80	Voltage Rating (V)	230	Zs (Ω)	0.42	Ipf (kA)	0.574	IΔn (ms)	N/A	
Main switch at this board												
BS(EN)	60947-3	Rating (A)	100	Voltage Rating (V)	230	Fault current rating (kA)	UNKNOWN	RCD Rating (mA)	N/A	IΔn (ms)	-	

CIRCUIT DETAILS

Cct No	Designation	No of points	Wiring type	Ref method	Conductors			Dis time (s)	Overcurrent devices					RCD	
					Live (mm ²)	cpc (mm ²)			BS(EN)	Rating (A)	Short circuit (kA)	Voltage Rating (V)	Max Zs (Ω)	RCD type	IΔn (mA)
1	Sprinkler	1	A	B	2.5	1.5		0.2	61009-C	20	6	230	0.87	AC	30
2	Heating	2	A	B	2.5	1.5		0.4	61009-B	16	6	230	2.2	AC	30
3	smoke alarms	17	A	100	1	1		0.4	61009-B	6	6	230	5.87	AC	30
4	shower 3	1	A	C	6	2.5		0.4	60898-B	32	6	230	1.10	AC	30
5	sockets 4 + 5	14	A	C	2.5	1.5		0.4	60898-B	16	6	230	2.2	AC	30
6	lights hall + 1	11	A	100	1.5	1		0.4	60898-B	6	6	230	5.87	AC	30
7	lights 2 + 3	8	A	100	1.5	1		0.4	60898-B	6	6	230	5.87	AC	30
8	shower 1	1	A	C	6	1.5		0.4	60898-B	32	6	230	1.10	AC	30
9	sockets 1, 2 + 3	15	A	C	2.5	1.5		0.4	60898-B	20	6	230	1.75	AC	30
10	lights 4 + 5	13	A	100	1.5	1		0.4	60898-B	6	6	230	5.87	AC	30

TEST RESULTS DB-1 - utility room - (MK 10 ways)

		Ring final circuits (measured end to end)			At least one column to be completed		Insulation resistance						RCD		AFDD	
Cct No	Designation	(r1) (Ω)	(rn) (Ω)	(r2) (Ω)	R1+R2 (Ω)	R2 (Ω)	IR Test voltage (V)	L-L (MΩ)	L-E (MΩ)	Polarity	Meas Zs (Ω)	Meas kA	RCD at IΔn (ms)	RCD Test button	AFDD Test button	Circuit vulnerable to test
1	Sprinkler	-	-	-	0.5	-	250	lim	200+	✓	0.92	-	18.6	✓	N/A	No
2	Heating	-	-	-	0.1	-	250	lim	200+	✓	0.52	-	28	✓	N/A	No
3	smoke alarms	-	-	-	lim	-	250	lim	200+	✓	lim	-	28	✓	N/A	Yes
4	shower 3	-	-	-	0.43	-	250	lim	91	✓	0.85	-	33.1	✓	N/A	No
5	sockets 4 + 5	0.58	0.60	0.99	-	-	250	lim	91	✓	0.71	-	33.1	✓	N/A	No
6	lights hall + 1	-	-	-	0.31	-	250	lim	91	✓	0.73	-	33.1	✓	N/A	Yes
7	lights 2 + 3	-	-	-	1.33	-	250	lim	91	✓	1.75	-	33.1	✓	N/A	Yes
8	shower 1	-	-	-	0.01	-	250	lim	9	✓	0.43	-	34.3	✓	N/A	No
9	sockets 1, 2 + 3	0.80	0.81	0.95	-	-	250	lim	9	✓	0.88	-	34.3	✓	N/A	No
10	lights 4 + 5	-	-	-	0.75	-	250	lim	9	✓	1.17	-	34.3	✓	N/A	Yes

ENGINEER AND TEST INSTRUMENTS

Multifunction

1995026

Continuity

-

Insulation resistance

-

EFLI Tester

-

RCD tester

-

Tested by (Capitals)

John Green

Signature

JRG

Date

28/11/2023

Report produced by electraform based on the MODEL FORM from BS7671:2018+A2:2022 (18th Edition)

ADDITIONAL BONDING INFORMATION

Water bond details

Water bond size

 mm²

Water bond measurement

 Ω

Water bond location

Additional notes

Gas bond details

Gas bond size

 mm²

Gas bond measurement

 Ω

Gas bond location

Additional notes

Oil bond details

Oil bond size

 mm²

Oil bond measurement

 Ω

Oil bond location

Additional notes

Structural steel bond details

Steel bond size

 mm²

Steel bond measurement

 Ω

Steel bond location

Additional notes

Lightning conductor bond details

Lightning conductor size

 mm²

Lightning conductor measurement

 Ω

Lightning conductor location(s)

Additional notes

Other bond details

Other bonding conductor size

 mm²

Bonding conductor measurement

 Ω

Other bonding conductor location(s)

Additional notes

CONDITION REPORT GUIDANCE FOR RECIPIENTS

This report is an important and valuable document which should be retained for future reference.

1. The purpose of this Report is to confirm, as far as reasonably practicable, whether or not the electrical installation is in a satisfactory condition for continued service (*see SUMMARY OF THE CONDITION OF THE INSTALLATION*). The Report should identify any damage, deterioration, defects, and / or conditions which may give rise to danger (*see OBSERVATIONS AND RECOMMENDATIONS*).
2. This Report is only valid if accompanied by the Inspection Schedule(s) and the Schedule(s) of Circuit Details and Test Results.
3. The person ordering the Report should have received this Report without watermarks and the inspector / company should have retained a duplicate.
4. This Report should be retained in a safe place and be made available to any person inspecting or undertaking work on the electrical installation in the future. If the property is vacated, this Report will provide the new owner / occupier with details of the condition of the electrical installation at the time the Report was issued.
5. The *EXTENT AND LIMITATIONS* section should identify fully the extent of the installation covered by this Report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the Report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.
6. Some operational limitations such as inability to gain access to parts of the installation or an item of equipment may have been encountered during the inspection. The inspector should have noted these in the *EXTENT AND LIMITATIONS* section.
7. For items classified in the *OBSERVATIONS AND RECOMMENDATIONS* section as C1 ("Danger present"), **the safety of those using the installation is at risk**, and it is recommended that a skilled person or persons competent in electrical installation work undertakes the necessary remedial work immediately.
8. For items classified in the *OBSERVATIONS AND RECOMMENDATIONS* section as C2 ("Potentially dangerous"), **the safety of those using the installation may be at risk**, and it is recommended that a skilled person or persons competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.
9. Where it has been stated in the *OBSERVATIONS AND RECOMMENDATIONS* section that an observation requires further investigation (Code FI) the inspection has revealed an apparent deficiency which may result in a Code C1 or C2, and could not, due to the extent or limitations of the inspection, be fully identified. Such observations should be investigated without delay. A further examination of the installation will be necessary, to determine the nature and extent of the apparent deficiency, (*see SUMMARY OF THE CONDITION OF THE INSTALLATION*)).
10. For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. The recommended date by which the next inspection is due can be found in the DECLARATION section of the Report.
11. **INTAKE EQUIPMENT (VISUAL INSPECTION ONLY)**
EXPLANATION OF CLASSIFICATION CODE X
An outcome against an item in this section, other than access to live parts, should NOT be used to determine the overall outcome.

NOTE 1: Where inadequacies in the intake equipment are encountered, which may result in a dangerous or potentially dangerous situation, the person ordering the work and / or duty holder must be informed. It is strongly recommended that the person ordering the work informs the appropriate authority.

NOTE 2: For this section only, where inadequacies are found, an X should be put against the appropriate item and a comment made in the Observations and Recommendations section.

12. Where the installation includes a Residual Current Device (RCD) it should be tested 6 monthly by pressing the button marked 'T' or 'Test'. The device should switch off the supply and should then be switched on to restore the supply. If the device does not switch off the supply when the button is pressed, seek expert advice. **For safety reasons it is important that this instruction is followed.**
13. Where the installation includes an Arc Fault Detection Device (AFDD) having a manual test facility it should be tested 6 monthly by pressing the test button. Where an AFDD has both a test button and automatic test function, manufacturer's instructions shall be followed with respect to test button operation.
14. Where the installation includes a Surge Protective Device (SPD) the status indicator should be checked to confirm it is in operational condition in accordance with manufacturer's information. If the indication shows that the device is not operational, seek expert advice. **For safety reasons it is important this safety instruction is followed.**
15. Where the installation includes alternative or additional sources of supply warning notices should be found at the origin or meter position or, if remote from the origin, at the consumer unit or distribution board and at all points of isolation of all sources of supply.

CODES FOR TYPE OF WIRING

A	B	C	D	E	F	G	H	O (Other)
Thermoplastic insulated/sheathed cables	Thermoplastic cables in metallic conduit	Thermoplastic cables in non-metallic conduit	Thermoplastic cables in metallic trunking	Thermoplastic cables in non-metallic trunking	Thermoplastic / SWA cables	Thermosetting / SWA cables	MICC cables	Other cable types not listed here
FP	TR	HT	SY	YY	CY	VIR		
FP 200 - standard fire resistant cable	Tri-rated - BS 6231 high temperature - flame retardant cable	Hi Tuff - waterproof with a tough PVC sheathing for outdoor use	SY cable - flexible instrumentation cable with a galvanised steel wire braid	YY cable - flexible instrumentation cable	CY cable - flexible instrumentation cable with a tinned copper wire braid and a PETP separator	VIR - Vulcanised Indian Rubber cable - no longer manufactured		

Report produced by electroform based on the MODEL FORM from BS7671:2018+A2:2022 (18th Edition)