
## ANKAA\_BASE BOARD


## **INDEX**

PAGE	DESCRIPTION
01	INDEX
02	BLOCK DIAGRAM
03	POWER FLOW DIAGRAM
04	CAM & MISC INTERFACE
05	DISPLAY INTERFACE
06	ETHERNET,CAN & SD INTERFACE
07	MINI_PCIE & SATA INTERFACE
08	USB & UART INTERFACE
09	AUDIO CODEC
10	REGULATORS
11	BOOT CONFIGURATION
12	SOM CONNECTOR
13	BOARD ACCESSORIES
14	REVISION HISTORY




e-con Confidential


## **BLOCK DIAGRAM**





ANKAA BASE BOARD





e-con Confidential











































\_\_\_\_\_

## **REVISION HISTORY**

Rev No	Date	Descript i on	Remarks
А	12 SEP 2014	Initial Release	
В	16 OCT 2014	Page NO: 4 U68, Level translator added for UART2 interface to provide option for 1.8V and 3.3V I/O FB43,FB42,C455,C456, R970,R972,R969,R974,R975,R971,R973 are added	
С	09 DEC 2014	Page NO: 5 LVDS1_INT and LVDS2_INT signals are changed to bidirectional.  U46 changed from 4 bit to 2 bit buffer  C18 changed from 47uF to 10uF  R347,R348,R349,R350,R978,R979,Q8,Q7 are added	
		Page NO: 8 UART Bridge changed from Self Powered to USB Bus powered D13, R980 added	
		Page NO: 10 U69, Open drain single bit buffer added to reset the audio codec when RESET switch is pressed R981 added	



e-con Confidential