





1 Battlement Front

Change view to vertical

















2 Battlement Front


Change view to vertical






Dimensions to outside








3 Battlement Side

attlement Side Change view to vertical












4 Battlement Side


Change view to vertical








Dimensions to outside 23/4" 23/4" 7/8" 7/8"















No alignment or dimensions in 27 Pimensionspicture here.
Make new materials thick black lines like the Isometric view. Now there is no contrast between allready built and new materials



Make detailview for screwposition

Place detailview for screwposition