

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL  
LOCATION : Yishun Ring Road/Ave 6  
DATE OF SERVICING : 31 /08/2025

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
  - 1.2 Check that breeching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

  - 2.1a When the rising main system or any portion thereof is out of service for any reason
  - 2.1b Notice shall be given to the SCDF
  - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

  - 3.1 Check the valve cabinets for damage

**Block No :**

**REMARKS**

BLK 398 Lift B Level 7 PVC cap missing need to Replace.  
BLK 395 Lift B Level 2 Bolt missing need to Replace.

Name & signature of Technician(s)

Verified By :

1 D.Pham P.D.P

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298 FAX : 6 287 9635

FAX : 6 287 9635

TOWN COUNCIL	:	<u>NEE SOON TOWN COUNCIL</u>
LOCATION	:	<u>Yishun Ring Road /Ave 6</u>
DATE OF SERVICING	:	<u>31 /08/2025</u>

## **HALF - YEARLY DRY RISER Checklist**

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

## 2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
  - 2.1b Notice shall be given to the SCDF

### 2.1c A sign to be displayed

- ### **3. VALVE CABINETS**

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

1 R.Ram

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

**TOWN COUNCIL** : NEE SOON TOWN COUNCIL  
**LOCATION** : Yishun Ring Road / Ave 6  
**DATE OF SERVICING** : 31 /08/2025

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breeching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary
  2. RISING SYSTEM
    - 2.1a When the rising main system or any portion thereof is out of service for any reason
    - 2.1b Notice shall be given to the SCDF
    - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
  - 2.2 Check the dry riser system for damaged pipes or valves
  3. VALVE CABINETS
    - 3.1 Check the valve cabinets for damage

**Block No :**

REMARKS

BLK 411 Level 9 -2-4 lock net spoil  
BLK 411 Level 6 2-4 lock net spoil  
BLK 408 #6 1254-1256 PVC cup spoil

Name & signature of Technician(s)

Verified By :

1 P Ram PP

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL  
LOCATION : Yishun Ave 11/ Yishun Ring Road  
DATE OF SERVICING : 31/08/2025

## **HALF - YEARLY DRY RISER Checklist**

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing

### 1.8 Inspect the ear

2. RISING SYSTEM

2.1a When the rising main system or any portion thereof is out of service for any reason

2.1b Notice shall be given to the SCDF

2.1c A sign to be displayed at each fire service connection to show portion of system out of order

## 2.2 Check the dry ri.

- ### 3. VALVE CABINETS

**Block No :**

**REMARKS**

BLK 455 Level 2 08-55 lock net spoil hood to Replace.  
BLK 469 B Level 11 stair case & door can't open.

Name & signature of Technician(s)

Verified By :

1 R. Ram P.P.

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun Ave 11
DATE OF SERVICING	:	31 /08/2025

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
  - 1.2 Check that breeching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary
  2. RISING SYSTEM
    - 2.1a When the rising main system or any portion thereof is out of service for any reason
    - 2.1b Notice shall be given to the SCDF
    - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
  - 2.2 Check the dry riser system for damaged pipes or valves
  3. VALVE CABINETS
    - 3.1 Check the valve cabinets for damage

**Block No :**

REMARKS

~~PEER 408~~ ~~Kiosk~~ ~~is~~ ~~broken~~ ~~is~~  
BLK 408 #12 unit no 12-66 PVC cap missing.

Name & signature of Technician(s)

Verified By :

1 P.Ram SP

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	<u>NEE SOON TOWN COUNCIL</u>
LOCATION	:	<u>Yishun Ave 11</u>
DATE OF SERVICING	:	<u>31 /08/2025</u>

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

  - 2.1a When the rising main system or any portion thereof is out of service for any reason
  - 2.1b Notice shall be given to the SCDF
  - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

  - 3.1 Check the valve cabinets for damage

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

## 1. P-PM 2.0 IT

(Name & signature)

2 \_\_\_\_\_

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	<u>NEE SOON TOWN COUNCIL</u>
LOCATION	:	<u>Yishun Ave 11</u>
DATE OF SERVICING	:	<u>31 /08/2025</u>

## **HALF - YEARLY DRY RISER Checklist**

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

## 2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
  - 2.1b Notice shall be given to the SCDF
  - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
  - 2.2 Check the dry riser system for damaged pipes or valves

**3. VALVE CABINETS**

  - 3.1 Check the valve cabinets for damage

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

1. P.Pan P.P

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL  
LOCATION : Yishun Ave 11/Ave 6  
DATE OF SERVICING : 31 /08/2025

## **HALF - YEARLY DRY RISER Checklist**

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary
  2. RISING SYSTEM
    - 2.1a When the rising main system or any portion thereof is out of service for any reason
    - 2.1b Notice shall be given to the SCDF
    - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
  - 2.2 Check the dry riser system for damaged pipes or valves
  3. VALVE CABINETS
    - 3.1 Check the valve cabinets for damage

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

1 R-Ron P.J.P

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	<u>NEE SOON TOWN COUNCIL</u>
LOCATION	:	<u>Yishun Ave 6/Ave 11</u>
DATE OF SERVICING	:	<u>31 /08/2025</u>

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
  - 1.2 Check that breeching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary
  2. RISING SYSTEM
    - 2.1a When the rising main system or any portion thereof is out of service for any reason
    - 2.1b Notice shall be given to the SCDF
    - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
  - 2.2 Check the dry riser system for damaged pipes or valves
  3. VALVE CABINETS
    - 3.1 Check the valve cabinets for damage

**Block No :**

REMARKS

Name & signature of Technician(s)

Verified By :

R.Dam R.P.

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	<u>NEE SOON TOWN COUNCIL</u>
LOCATION	:	<u>Yishun Ring Road/Ave 11</u>
DATE OF SERVICING	:	<u>31 /08/2025</u>

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breeching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary
  2. RISING SYSTEM
    - 2.1a When the rising main system or any portion thereof is out of service for any reason
    - 2.1b Notice shall be given to the SCDF
    - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
  - 2.2 Check the dry riser system for damaged pipes or valves
  3. VALVE CABINETS
    - 3.1 Check the valve cabinets for damage

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

1

(Name & signature)

2

**RED-POWER ELECTRICAL ENGINEERING PTE LTD**

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun St 41
DATE OF SERVICING	:	31 /08/2025

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

  - 2.1a When the rising main system or any portion thereof is out of service for any reason
  - 2.1b Notice shall be given to the SCDF
  - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

  - 3.1 Check the valve cabinets for damage

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

1 R<sub>RPm</sub> D<sub>1</sub>

(Name & signature)

2

**RED-POWER ELECTRICAL ENGINEERING PTE LTD**

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	<u>NEE SOON TOWN COUNCIL</u>
LOCATION	:	<u>Yishun Ave 6</u>
DATE OF SERVICING	:	<u>21 /08/2025</u>

## **HALF - YEARLY DRY RISER Checklist**

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

## 2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason  
2.1b Notice shall be given to the SCDF

### 3. VALVE CABINETS

- ### 3. VALVE CABINETS

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

1. ~~Ron S.~~

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun Ave 6/ Yishun St 43
DATE OF SERVICING	:	31 /08/2025

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

## 2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
  - 2.1b Notice shall be given to the SCDF
  - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
  - 2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

  - 3.1 Check the valve cabinets for damage

REMARKS

Name & signature of Technician(s)

Verified By :

1 R.Ram PT

(Name & signature)

2

**Block No :**

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun St 42
DATE OF SERVICING	:	31 /08/2025

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
  - 1.2 Check that breeching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary
  2. RISING SYSTEM
    - 2.1a When the rising main system or any portion thereof is out of service for any reason
    - 2.1b Notice shall be given to the SCDF
    - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
  - 2.2 Check the dry riser system for damaged pipes or valves
  3. VALVE CABINETS
    - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

1 R.PAm PEP

(Name & signature)

2 \_\_\_\_\_

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298 FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL  
LOCATION : Yishun St 44  
DATE OF SERVICING : 31 /08/2025

## HALF - YEARLY DRY RISER Checklist

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
  - 1.2 Check that breeching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

  - 2.1a When the rising main system or any portion thereof is out of service for any reason
  - 2.1b Notice shall be given to the SCDF
  - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

  - 3.1 Check the valve cabinets for damage

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

1 R.Ram R

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL  
LOCATION : Yishun St 44  
DATE OF SERVICING : 31/08/2025

## **HALF - YEARLY DRY RISER Checklist**

## 1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
  - 1.2 Check that breaching inlets and landing valves are not obstructed
  - 1.3 Check and verify landing valves are fully enclosed
  - 1.4 Check and verify handwheels are strapped locked
  - 1.5 Check that valve caps are provided and secured in position
  - 1.6 Check rubber washers of the outlets and replace them if missing
  - 1.7 Check handwheels to ensure that they are not jammed or missing
  - 1.8 Inspect the earthing connection and tighten it if necessary

## 2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason  
2.1b Notice shall be given to the SCDF

### 2.1c A sign to be dis

3. VALVE CABINETS
  - 3.1 Check the valve cabinets for damage

**Block No :**

**REMARKS**

Name & signature of Technician(s)

Verified By :

1 R.Ramak

(Name & signature)

2