

BED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10, #01 - 364, SINGAPORE 539197

TEL : 6 289 2298 FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun St 21
DATE OF SERVICING : 17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

MARKS
B12 209 Level 12 Lift c Bolt and lock missing need to
Replace.

Name & signature of Technician(s)

1 8

Verified By :

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10, #01 - 364, SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun St 21
DATE OF SERVICING : 15/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breeching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary
 2. RISING SYSTEM
 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves
 3. VALVE CABINETS
 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

1

ure of Technici

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298 FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun St 21
DATE OF SERVICING	:	17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

1 Rff.

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun St 21
DATE OF SERVICING : 12/08/2025

HALF - YEARLY DRY RISER Checklist

- 1. INLETS & VALVES**
 - 1.1 Check and verify operation of fire brigade breeching inlets
 - 1.2 Check that breeching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary
 - 2. RISING SYSTEM**
 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves**
 - 3. VALVE CABINETS**
 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

1 Pf

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298 FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun Ring Road / Yishun Ave 9
DATE OF SERVICING	:	17/08/2025

HALF - YEARLY DRY RISER Checklist

- 1. INLETS & VALVES**
 - 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breeching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary
 - 2. RISING SYSTEM**
 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves**
 - 3. VALVE CABINETS**
 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

BLK 243 Level & lock missing need to replace

BLK 242 Level 10 lock missing / need to Replace

PLK 2A Level 2 Belt & lock missing need to Replace

Name & signature of Technician(s)

Verified By :

RH

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun Ave 9/Yishun Ring Road
DATE OF SERVICING : 17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
 - 1.2 Check that breeching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary
 2. RISING SYSTEM
 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves
 3. VALVE CABINETS
 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

Df

(Name & signature)

2

BLK 255 Level 6 & 7 Belt & lock missing need to
Replace.

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun St 22
DATE OF SERVICING	:	17 /08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

REMARKS

~~BLK-260 Level-2 belt + lock missing, 262-2 level-2 belt + lock missing~~
~~BLK-269A - level-2 belt + lock missing, 269B level-3 belt + lock missing.~~

Name & signature of Technician(s)

Verified By :

1 RH.

(Name & signature)

2 _____

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun St 20/Yishun Central
DATE OF SERVICING	:	15 /08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

BX-299 - Level-12 PVC cover missing.

Name & signature of Technician(s)

1 Pf.

Verified By :

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun Ring Road/Yishun Central
DATE OF SERVICING : 15/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
 - 1.2 Check that breeching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the seating connection and tighten it if necessary

2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
2.1b Notice shall be given to the SCDF
2.1c A sign to be displayed at each fire service connection to show portion of system out of order

3. VALVE CABINETS

- ### 3. VALVE CABINETS
- #### 3.1 Check the valve cabinets for damage

Block No :

308	309	310	311	312	314	320	321
	<img alt="Handwritten mark for cell 309, row 68						

REMARKS

BLK 309 Level 2 - 2 PVC cup missing, Level 3 PVC cup missing.
head to Replace. BLK 311 Level 2 Lift B belt missing
need to Replace.

Name & signature of Technician(s)

Verified By :

1 Rf

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun Central/Yishun Ring Road
DATE OF SERVICING	:	17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
 - 1.2 Check that breeching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary
 2. RISING SYSTEM
 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves
 3. VALVE CABINETS
 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

B16 329 Level 6 lift A back net missing. P need to replace.

Name & signature of Technician(s)

Verified By :

1 RK

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	<u>NEE SOON TOWN COUNCIL</u>
LOCATION	:	<u>Yishun Ring Road</u>
DATE OF SERVICING	:	<u>17 /08/2025</u>

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary
 2. RISING SYSTEM
 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves
 3. VALVE CABINETS
 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

1 Rf.

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun Ave 11
DATE OF SERVICING : 17 /08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

1

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun Ave 11/Yishun Ring Road
DATE OF SERVICING : 17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order
 - 2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

Block No :

348D	349	350	351	352	353	354	355
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							

REMARKS

Name & signature of Technician(s)

Verified By :

1 24

(Name & signature)

2

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun Ring Road
DATE OF SERVICING : 17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

 - 2.1a When the rising main system or any portion thereof is out of service
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show position
 - 2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

BLK- 363 - Lift A - Level-6 PVC cover missing.
BLK- 363 - Lift B - Level-7 PVC cover missing.

Name & signature of Technician(s)

P/H

Verified By :

(Name & signature)

2



Blk 363, st,6)life, A

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun Ring Road / Ave 9
DATE OF SERVICING : 17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF

3. VALVE CABINETS

- ### 3. VALVE CABINETS
- #### 3.1 Check the valve cabinets for damage.

Block No :

REMARKS

Name & signature of Technician(s)

1 Df.

Verified By :

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10, #01 - 364, SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun Ring Road/Ave 9
DATE OF SERVICING	:	18/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser

- ### 3. VALVE CABINETS

Block No :

REMARKS

Name & signature of Technician(s)

& signature of technician(s)

1 

2

Verified By

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298 FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun St 31
DATE OF SERVICING : 17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

3. VALVE CABINETS

- ### 3. VALVE CABINETS

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

1 

(Name & signature)

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298 FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun St 31
DATE OF SERVICING : 15 /08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breeching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

Name & signature of Technician(s)

Verified By :

1

(Name & signature)

2

REDPOWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL : NEE SOON TOWN COUNCIL
LOCATION : Yishun Ring Road
DATE OF SERVICING : 17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breeching inlets
 - 1.2 Check that breeching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

 - 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF
 - 2.1c A sign to be displayed at each fire service connection to show portion of system out of order

2.2 Check the dry riser system for damaged pipes or valves

3. VALVE CABINETS

 - 3.1 Check the valve cabinets for damage

Block No :

REMARKS

BLK 382B 2-2 #6 pvc cuff & pull.
BLK - 382 1-2 #2 dry riser door can't open.

Name & signature of Technician(s)

Verified By :

1 _____

(Name & signature)



Blk 382C level 5 ,1-2,
can't open

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL	:	NEE SOON TOWN COUNCIL
LOCATION	:	Yishun Ave 6
DATE OF SERVICING	:	17/08/2025

HALF - YEARLY DRY RISER Checklist

1. INLETS & VALVES

- 1.1 Check and verify operation of fire brigade breaching inlets
 - 1.2 Check that breaching inlets and landing valves are not obstructed
 - 1.3 Check and verify landing valves are fully enclosed
 - 1.4 Check and verify handwheels are strapped locked
 - 1.5 Check that valve caps are provided and secured in position
 - 1.6 Check rubber washers of the outlets and replace them if missing
 - 1.7 Check handwheels to ensure that they are not jammed or missing
 - 1.8 Inspect the earthing connection and tighten it if necessary

2. RISING SYSTEM

- 2.1a When the rising main system or any portion thereof is out of service for any reason
 - 2.1b Notice shall be given to the SCDF

3. VALVE CABINETS

- ### 3. VALVE CABINETS

Block No :

REMARKS

Name & signature of Technician(s)

1

Verified By :

(Name & signature)

2