

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

NEE SOON TOWN COUNCIL

CHONG PANG DIVISION

/09/2025

1. SIMULATED TEST
 - 1.1 Carry out a stimulated fire alarm call
 - 1.2 Operate any Alarm Zone
 - 1.3 Transmit a Fire Alarm Signal to the monitoring station and reset the system
 - 1.4 Simulate fire conditions on all alarm zones and reset the system to normal
 - 1.5 Disconnect battery and ensure visual & audible fault signals activated at main alarm panel
 - 1.6 Simulate main power failure and ensure system operate correctly with the standby battery power
 - 1.7 Simulate the fire alarm conditions and check the output signals availability
 - 1.8 Remote ancillary function is initiated during the fire alarm condition simulation test
 - 1.9 Simulate fault condition on all alarm zones to ensure main alarm panel is operating correctly
2. MONITORING STATION
 - 2.1 Contact the monitoring system prior to the transmitting of the fire alarm signal
 - 2.2 To warn them of the simulated fire condition to be tested
 - 2.3 Check & confirm with them after completion of test to ensure the fire alarm signal was received
 - 2.4 Advise the monitoring station that the system has been reset
 - 2.5 Notify them of intention to test and shut down the fire alarm system if applicable
3. BATTERY CONDITION
 - 3.1 Check the battery voltage in accordance with the manufacturer's instructions
 - 3.2 Check the battery conditions
 - 3.3 Check battery charging current in accordance with the manufacturer's instructions
 - 3.4 Check batteries and their terminals as specified by the manufacturer
 - 3.5 Ensure batteries and their terminals are in good servicable condition
 - 3.6 Examine to ensure that the specific gravity in each cell is correct
 - 3.7 Examine to ensure the level of the electrolyte in each cell is correct
 - 3.8 Check condition of battery cabinet for corrosion
 - 3.9 Ensure that batteries are stored in a secure condition
4. INDICATING LIGHTS
 - 4.1 Ensure that all indicating lights are operating correctly
 - 4.2 Replace any faulty indicating lights if any
5. SOUNDS
 - 5.1 Check operation of all alarm sounders
6. MAIN ALARM SYSTEM
 - 6.1 Check the main alarm panel is in a clean and operative condition
 - 6.2 Visually inspect the condition of components, terminations and cables
 - 6.3 Ensure that faulty parts are replaced
 - 6.4 Ensure that replacement has been carried out satisfactorily
7. SWITCHES
 - 7.1 Ensure that all switches are in the correct operating condition after completion of tests
 - 7.2 Take immediate steps to rectify the fault(s) should they exist
8. SMOKE DETECTORS
 - 8.1 Clean all smoke detectors every four months
9. DEFECTS
 - 9.1 Record in the log any fault(s) identified and that the above test has been carried out


[illegible]

Verified By :

1

2

(Name & signature)



RED POWER
R.V.RAM


11:19

Wed
10/09/2025

105 Yishun Ring Rd

Timemark App
Authentic time, GPS

© MPDLGB9EE6ED4K Timemark Verified



RED POWER
R.V.RAM

11:25 Wed
10/09/2025


■ 105 Yishun Ring Rd

Timemark App
Authentic time, GPS

2 _____

2 _____

BUK-104 (Mandel) Fire Extinguisher need to top up.



DIGI CORPORATION PTE LTD
14 Serangoon Road, Singapore 556118
Tel: 6752 7437 Fax: 6753 7879

Date	Checked By	Remarks
Apr 6	CP	
May 6	CP	
Jun 6	CP	
Jul 6	CP	
Aug 6	CP	
Sep 6	CP	
Oct 6	CP	
Nov 6	CP	
Dec 6	CP	
Jan 7	CP	
Feb 7	CP	
Mar 7	CP	
Apr 7	CP	
May 7	CP	
Jun 7	CP	
Jul 7	CP	
Aug 7	CP	
Sep 7	CP	
Oct 7	CP	
Nov 7	CP	
Dec 7	CP	
Jan 8	CP	
Feb 8	CP	
Mar 8	CP	
Apr 8	CP	
May 8	CP	
Jun 8	CP	
Jul 8	CP	
Aug 8	CP	
Sep 8	CP	
Oct 8	CP	
Nov 8	CP	
Dec 8	CP	
Jan 9	CP	
Feb 9	CP	
Mar 9	CP	
Apr 9	CP	
May 9	CP	
Jun 9	CP	
Jul 9	CP	
Aug 9	CP	
Sep 9	CP	
Oct 9	CP	
Nov 9	CP	
Dec 9	CP	
Jan 10	CP	
Feb 10	CP	
Mar 10	CP	
Apr 10	CP	
May 10	CP	
Jun 10	CP	
Jul 10	CP	
Aug 10	CP	
Sep 10	CP	
Oct 10	CP	
Nov 10	CP	
Dec 10	CP	
Jan 11	CP	
Feb 11	CP	
Mar 11	CP	
Apr 11	CP	
May 11	CP	
Jun 11	CP	
Jul 11	CP	
Aug 11	CP	
Sep 11	CP	
Oct 11	CP	
Nov 11	CP	
Dec 11	CP	
Jan 12	CP	
Feb 12	CP	
Mar 12	CP	
Apr 12	CP	
May 12	CP	
Jun 12	CP	
Jul 12	CP	
Aug 12	CP	
Sep 12	CP	
Oct 12	CP	
Nov 12	CP	
Dec 12	CP	
Jan 13	CP	
Feb 13	CP	
Mar 13	CP	
Apr 13	CP	
May 13	CP	
Jun 13	CP	
Jul 13	CP	
Aug 13	CP	
Sep 13	CP	
Oct 13	CP	
Nov 13	CP	
Dec 13	CP	
Jan 14	CP	
Feb 14	CP	
Mar 14	CP	
Apr 14	CP	
May 14	CP	
Jun 14	CP	
Jul 14	CP	
Aug 14	CP	
Sep 14	CP	
Oct 14	CP	
Nov 14	CP	
Dec 14	CP	
Jan 15	CP	
Feb 15	CP	
Mar 15	CP	
Apr 15	CP	
May 15	CP	
Jun 15	CP	
Jul 15	CP	
Aug 15	CP	
Sep 15	CP	
Oct 15	CP	
Nov 15	CP	
Dec 15	CP	
Jan 16	CP	
Feb 16	CP	
Mar 16	CP	
Apr 16	CP	
May 16	CP	
Jun 16	CP	
Jul 16	CP	
Aug 16	CP	
Sep 16	CP	
Oct 16	CP	
Nov 16	CP	
Dec 16	CP	
Jan 17	CP	
Feb 17	CP	
Mar 17	CP	
Apr 17	CP	
May 17	CP	
Jun 17	CP	
Jul 17	CP	
Aug 17	CP	
Sep 17	CP	
Oct 17	CP	
Nov 17	CP	
Dec 17	CP	
Jan 18	CP	
Feb 18	CP	
Mar 18	CP	
Apr 18	CP	
May 18	CP	
Jun 18	CP	
Jul 18	CP	
Aug 18	CP	
Sep 18	CP	
Oct 18	CP	
Nov 18	CP	
Dec 18	CP	
Jan 19	CP	
Feb 19	CP	
Mar 19	CP	
Apr 19	CP	
May 19	CP	
Jun 19	CP	
Jul 19	CP	
Aug 19	CP	
Sep 19	CP	
Oct 19	CP	
Nov 19	CP	
Dec 19	CP	
Jan 20	CP	
Feb 20	CP	
Mar 20	CP	
Apr 20	CP	
May 20	CP	
Jun 20	CP	
Jul 20	CP	
Aug 20	CP	
Sep 20	CP	
Oct 20	CP	
Nov 20	CP	
Dec 20	CP	
Jan 21	CP	
Feb 21	CP	
Mar 21	CP	
Apr 21	CP	
May 21	CP	
Jun 21	CP	
Jul 21	CP	
Aug 21	CP	
Sep 21	CP	
Oct 21	CP	
Nov 21	CP	
Dec 21	CP	
Jan 22	CP	
Feb 22	CP	
Mar 22	CP	
Apr 22	CP	
May 22	CP	
Jun 22	CP	
Jul 22	CP	
Aug 22	CP	
Sep 22	CP	
Oct 22	CP	
Nov 22	CP	
Dec 22	CP	
Jan 23	CP	
Feb 23	CP	
Mar 23	CP	
Apr 23	CP	
May 23	CP	
Jun 23	CP	
Jul 23	CP	
Aug 23	CP	
Sep 23	CP	
Oct 23	CP	
Nov 23	CP	
Dec 23	CP	
Jan 24	CP	
Feb 24	CP	
Mar 24	CP	
Apr 24	CP	
May 24	CP	
Jun 24	CP	
Jul 24	CP	
Aug 24	CP	
Sep 24	CP	
Oct 24	CP	
Nov 24	CP	
Dec 24	CP	
Jan 25	CP	
Feb 25	CP	
Mar 25	CP	
Apr 25	CP	
May 25	CP	
Jun 25	CP	
Jul 25	CP	
Aug 25	CP	
Sep 25	CP	
Oct 25	CP	
Nov 25	CP	
Dec 25	CP	



RED POWER
DURAI

13:42 Wed
10/09/2025

107 Yishun Ring Rd

Timemark App
Authentic time, GPS



© 13GN39URMTNTEN Timemark Verified




RED POWER
DURAI

10:51 Wed
10/09/2025

■ 109 Yishun Ring Road,
760109

Timemark App
Authentic time, GPS



DIGI CORPORATION PTE LTD
14 Serangoon Road, Singapore 556114
Tel: 6752 7437 Fax: 6753 7879

Date	Checked By	Remarks
Apr 6	CP	
May 6	CP	
Jun 6	CP	
Jul 6	CP	
Aug 6	CP	
Sep 6	CP	
Oct 6	CP	
Nov 6	CP	
Dec 6	CP	
Jan 7	CP	
Feb 7	CP	
Mar 7	CP	
Apr 7	CP	
May 7	CP	
Jun 7	CP	
Jul 7	CP	
Aug 7	CP	
Sep 7	CP	
Oct 7	CP	
Nov 7	CP	
Dec 7	CP	
Jan 8	CP	
Feb 8	CP	
Mar 8	CP	
Apr 8	CP	
May 8	CP	
Jun 8	CP	
Jul 8	CP	
Aug 8	CP	
Sep 8	CP	
Oct 8	CP	
Nov 8	CP	
Dec 8	CP	
Jan 9	CP	
Feb 9	CP	
Mar 9	CP	
Apr 9	CP	
May 9	CP	
Jun 9	CP	
Jul 9	CP	
Aug 9	CP	
Sep 9	CP	
Oct 9	CP	
Nov 9	CP	
Dec 9	CP	
Jan 10	CP	
Feb 10	CP	
Mar 10	CP	
Apr 10	CP	
May 10	CP	
Jun 10	CP	
Jul 10	CP	
Aug 10	CP	
Sep 10	CP	
Oct 10	CP	
Nov 10	CP	
Dec 10	CP	
Jan 11	CP	
Feb 11	CP	
Mar 11	CP	
Apr 11	CP	
May 11	CP	
Jun 11	CP	
Jul 11	CP	
Aug 11	CP	
Sep 11	CP	
Oct 11	CP	
Nov 11	CP	
Dec 11	CP	
Jan 12	CP	
Feb 12	CP	
Mar 12	CP	
Apr 12	CP	
May 12	CP	
Jun 12	CP	
Jul 12	CP	
Aug 12	CP	
Sep 12	CP	
Oct 12	CP	
Nov 12	CP	
Dec 12	CP	
Jan 13	CP	
Feb 13	CP	
Mar 13	CP	
Apr 13	CP	
May 13	CP	
Jun 13	CP	
Jul 13	CP	
Aug 13	CP	
Sep 13	CP	
Oct 13	CP	
Nov 13	CP	
Dec 13	CP	
Jan 14	CP	
Feb 14	CP	
Mar 14	CP	
Apr 14	CP	
May 14	CP	
Jun 14	CP	
Jul 14	CP	
Aug 14	CP	
Sep 14	CP	
Oct 14	CP	
Nov 14	CP	
Dec 14	CP	
Jan 15	CP	
Feb 15	CP	
Mar 15	CP	
Apr 15	CP	
May 15	CP	
Jun 15	CP	
Jul 15	CP	
Aug 15	CP	
Sep 15	CP	
Oct 15	CP	
Nov 15	CP	
Dec 15	CP	
Jan 16	CP	
Feb 16	CP	
Mar 16	CP	
Apr 16	CP	
May 16	CP	
Jun 16	CP	
Jul 16	CP	
Aug 16	CP	
Sep 16	CP	
Oct 16	CP	
Nov 16	CP	
Dec 16	CP	
Jan 17	CP	
Feb 17	CP	
Mar 17	CP	
Apr 17	CP	
May 17	CP	
Jun 17	CP	
Jul 17	CP	
Aug 17	CP	
Sep 17	CP	
Oct 17	CP	
Nov 17	CP	
Dec 17	CP	
Jan 18	CP	
Feb 18	CP	
Mar 18	CP	
Apr 18	CP	
May 18	CP	
Jun 18	CP	
Jul 18	CP	
Aug 18	CP	
Sep 18	CP	
Oct 18	CP	
Nov 18	CP	
Dec 18	CP	
Jan 19	CP	
Feb 19	CP	
Mar 19	CP	
Apr 19	CP	
May 19	CP	
Jun 19	CP	
Jul 19	CP	
Aug 19	CP	
Sep 19	CP	
Oct 19	CP	
Nov 19	CP	
Dec 19	CP	
Jan 20	CP	
Feb 20	CP	
Mar 20	CP	
Apr 20	CP	
May 20	CP	
Jun 20	CP	
Jul 20	CP	
Aug 20	CP	
Sep 20	CP	
Oct 20	CP	
Nov 20	CP	
Dec 20	CP	
Jan 21	CP	
Feb 21	CP	
Mar 21	CP	
Apr 21	CP	
May 21	CP	
Jun 21	CP	
Jul 21	CP	
Aug 21	CP	
Sep 21	CP	
Oct 21	CP	
Nov 21	CP	
Dec 21	CP	
Jan 22	CP	
Feb 22	CP	
Mar 22	CP	
Apr 22	CP	
May 22	CP	
Jun 22	CP	
Jul 22	CP	
Aug 22	CP	
Sep 22	CP	
Oct 22	CP	
Nov 22	CP	
Dec 22	CP	
Jan 23	CP	
Feb 23	CP	
Mar 23	CP	
Apr 23	CP	
May 23	CP	
Jun 23	CP	
Jul 23	CP	
Aug 23	CP	
Sep 23	CP	
Oct 23	CP	
Nov 23	CP	
Dec 23	CP	
Jan 24	CP	
Feb 24	CP	
Mar 24	CP	
Apr 24	CP	
May 24	CP	
Jun 24	CP	
Jul 24	CP	
Aug 24	CP	
Sep 24	CP	
Oct 24	CP	
Nov 24	CP	
Dec 24	CP	
Jan 25	CP	
Feb 25	CP	
Mar 25	CP	
Apr 25	CP	
May 25	CP	
Jun 25	CP	
Jul 25	CP	
Aug 25	CP	
Sep 25	CP	
Oct 25	CP	
Nov 25	CP	
Dec 25	CP	
Jan 26	CP	
Feb 26	CP	
Mar 26	CP	
Apr 26	CP	
May 26	CP	
Jun 26	CP	
Jul 26	CP	
Aug 26	CP	
Sep 26	CP	
Oct 26	CP	
Nov 26	CP	
Dec 26	CP	
Jan 27	CP	
Feb 27	CP	
Mar 27	CP	
Apr 27	CP	
May 27	CP	
Jun 27	CP	
Jul 27	CP	
Aug 27	CP	
Sep 27	CP	
Oct 27	CP	
Nov 27	CP	
Dec 27	CP	
Jan 28	CP	
Feb 28	CP	
Mar 28	CP	
Apr 28	CP	
May 28	CP	
Jun 28	CP	
Jul 28	CP	
Aug 28	CP	
Sep 28	CP	
Oct 28	CP	
Nov 28	CP	
Dec 28	CP	
Jan 29	CP	
Feb 29	CP	
Mar 29	CP	
Apr 29	CP	
May 29	CP	
Jun 29	CP	
Jul 29	CP	
Aug 29	CP	
Sep 29	CP	
Oct 29	CP	
Nov 29	CP	
Dec 29	CP	
Jan 30	CP	
Feb 30	CP	
Mar 30	CP	
Apr 30	CP	
May 30	CP	
Jun 30	CP	
Jul 30	CP	
Aug 30	CP	
Sep 30	CP	
Oct 30	CP	
Nov 30	CP	
Dec 30	CP	
Jan 31	CP	
Feb 31	CP	
Mar 31	CP	
Apr 31	CP	
May 31	CP	
Jun 31	CP	
Jul 31	CP	
Aug 31	CP	
Sep 31	CP	
Oct 31	CP	
Nov 31	CP	
Dec 31	CP	




RED POWER
DURAI

13:42 Wed
10/09/2025

107 Yishun Ring Rd

Timemark App
Authentic time, GPS

© MCEW3T1CRPBCCGY Timemark Verified




RED POWER
R.V.RAM

11:25 Wed
10/09/2025

■ 105 Yishun Ring Rd

Timemark App
Authentic time, GPS



RED POWER
R.V.RAM

11:19 Wed
10/09/2025
105 Yishun Ring Rd

Timemark App
Authentic time, GPS

© MPDLGB9EE6ED4K Timemark Verified

(Name & signature)

**Blk 113 switch room 2 fire
extinguisher missing**



**RED POWER
DURAI**

15:37 Wed
10/09/2025

■ 113 Yishun Ring Road,
760113

Timemark App
Authentic time, GPS

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

NEE SOON TOWN COUNCIL

CHONG PANG DIVISION

/09/2025

1. QUALIFIED PERSON
- 1.1 All servicing and recharging of fire extinguishers shall only be performed by qualified person
- 1.2 Qualified person must belong to companies approved by Singapore Civil Defence Force
- 1.3 Carry out maintenance as specified in CP 55: 1991
2. FIRE EXTINGUISHERS
- 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
- 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
- 2.2 All fire extinguishers have not been discharged or lost pressure
- 2.3 Access to and visibility of each extinguishers is not obstructed
- 2.4 Operating instructions on each extinguishers surface shall be legible and faced outward
- 2.5 Pressure gauge readings if any shall be in the operable range
- 2.6 Any seals, safety clip or tamper indicators that are broken or missing shall be replaced
- 2.7 Any physical damage, corrosion, leakage or clogged nozzle shall be rectified
- 2.8 Damaged, broken or rusty fire extinguishers shall be repaired or replaced
- 2.9 Keep inspection records for those extinguishers that are found to require corrective actions
- 2.10 Submit inspection records to Superintending Officer
- 2.11 All extinguishers are to be properly hung
- 2.12 Date of service is shown and has not expired
- 2.13 The extinguishers shall bear a PSB label

Block No :							
123	124	125	126	127	128	129	130
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							

Verified By :

1 Selva of

2

(Name & signature)

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

NEE SOON TOWN COUNCIL

CHONG PANG DIVISION

2 /09/2025

1. QUALIFIED PERSON

- 1.1 All servicing and recharging of fire extinguishers shall only be performed by qualified person
- 1.2 Qualified person must belong to companies approved by Singapore Civil Defence Force
- 1.3 Carry out maintenance as specified in CP 55: 1991
2. FIRE EXTINGUISHERS
 - 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
 - 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
 - 2.2 All fire extinguishers have not been discharged or lost pressure
 - 2.3 Access to and visibility of each extinguishers is not obstructed
 - 2.4 Operating instructions on each extinguishers surface shall be legible and faced outward
 - 2.5 Pressure gauge readings if any shall be in the operable range
 - 2.6 Any seals, safety clip or tamper indicators that are broken or missing shall be replaced
 - 2.7 Any physical damage, corrosion, leakage or clogged nozzle shall be rectified
 - 2.8 Damaged, broken or rusty fire extinguishers shall be repaired or replaced
 - 2.9 Keep inspection records for those extinguishers that are found to require corrective actions
 - 2.10 Submit inspection records to Superintending Officer
 - 2.11 All extinguishers are to be properly hung
 - 2.12 Date of service is shown and has not expired
 - 2.13 The extinguishers shall bear a PSB label

139	140	141	142	143	144	145	146
</							

REMARKS

Name & signature of Technician(s)

Verified By :

1 Solva by

2

(Name & signature)

(Name & signature)

**Blk 153 lift room fire
extinguisher need to top
up**




**RED POWER
DURAI**

15:40 Mon
15/09/2025

■ 153 Yishun Street 21

Timemark App
Authentic time, GPS

**Blk 162 RHE fire
extinguisher missing**



**RED POWER
DURAI**

10:26 Sat
13/09/2025

■ Bakkar Turkish Kebab, 162
Yishun Street 11, #08-270,
760162

Timemark App
Authentic time, GPS

(Name & signature)

**Blk 165 court, fire
extinguisher key glass
broken need to replace**

FIRE EXTINGUISHER



**RED POWER
DURAI**

10:19 Tues
16/09/2025

■ 165 Yishun Ring Rd

Timemark App
Authentic time, GPS

**Blk 165 court, fire
extinguisher , ABC dry
powder need to top up**



**RED POWER
DURAI**

10:13 Tues
16/09/2025

■ BlueSG, 165 Yishun Ring
Road, 760165

Timemark App
Authentic time, GPS

**Blk 165 court, fire
extinguisher ABC dry
powder need to top up**



**RED POWER
DURAI**

10:13 Tues
16/09/2025

■ BlueSG, 165 Yishun Ring
Road, 760165

Timemark App
Authentic time, GPS

**Blk 165 court, fire
extinguisher ABC dry
powder need to top up**



**RED POWER
DURAI**

10:18 Tues
16/09/2025

■ 165 Yishun Ring Rd

Timemark App
Authentic time, GPS

**Blk 165 court, fire
extinguisher , ABC dry
powder need to top up**



**RED POWER
DURAI**

10:13 Tues
16/09/2025

■ BlueSG, 165 Yishun Ring
Road, 760165

Timemark App
Authentic time, GPS

(Name & signature)

**Blk 165 court, fire
extinguisher key glass
broken need to replace**

FIRE EXTINGUISHER




**RED POWER
DURAI**

10:19 Tues
16/09/2025

■ 165 Yishun Ring Rd

Timemark App
Authentic time, GPS

**Blk 162 RHE fire
extinguisher missing**



**RED POWER
DURAI**

10:26 Sat
13/09/2025

■ Bakkar Turkish Kebab, 162
Yishun Street 11, #08-270,
760162

Timemark App
Authentic time, GPS

**Blk 153 lift room fire
extinguisher need to top
up**



**RED POWER
DURAI**

15:40 Mon
15/09/2025

■ 153 Yishun Street 21

Timemark App
Authentic time, GPS

**Blk 113 switch room 2 fire
extinguisher missing**




RED POWER
DURAI

15:37 Wed
10/09/2025

■ 113 Yishun Ring Road,
760113

Timemark App
Authentic time, GPS



RED POWER
R.V.RAM


11:19

Wed
10/09/2025

105 Yishun Ring Rd

Timemark App
Authentic time, GPS

© MPDLGB9EE6ED4K Timemark Verified



RED POWER
R.V.RAM

11:25 Wed
10/09/2025

■ 105 Yishun Ring Rd

Timemark App
Authentic time, GPS

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

LOCATION CHONG PANG DIVISION

DATE OF SERVICING 3 /09/2025

1. QUALIFIED PERSON
 - 1.1 All servicing and recharging of fire extinguishers shall only be performed by qualified person
 - 1.2 Qualified person must belong to companies approved by Singapore Civil Defence Force
 - 1.3 Carry out maintenance as specified in CP 55: 1991
2. FIRE EXTINGUISHERS
 - 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
 - 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
 - 2.2 All fire extinguishers have not been discharged or lost pressure
 - 2.3 Access to and visibility of each extinguishers is not obstructed
 - 2.4 Operating instructions on each extinguishers surface shall be legible and faced outward
 - 2.5 Pressure gauge readings if any shall be in the operable range
 - 2.6 Any seals, safety clip or tamper indicators that are broken or missing shall be replaced
 - 2.7 Any physical damage, corrosion, leakage or clogged nozzle shall be rectified
 - 2.8 Damaged, broken or rusty fire extinguishers shall be repaired or replaced
 - 2.9 Keep inspection records for those extinguishers that are found to require corrective actions
 - 2.10 Submit inspection records to Superintending Officer
 - 2.11 All extinguishers are to be properly hung
 - 2.12 Date of service is shown and has not expired
 - 2.13 The extinguishers shall bear a PSB label

[illegible]

REMARKS

Name & signature of Technician(s)

1 Helina Sel.

2

Verified By :

(Name & signature)

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

NEE SOON TOWN COUNCIL

CHONG PANG DIVISION

2/09/2025

1. GENERAL

1.1a If any part of DECAM equipment supplied by DECAM sub-con become defective/repairs required

1.1b Contractor shall carry out all the repairs and replacement of parts at its own expense

2. ALARM

2.1 Monitor the Premises 24 hours daily for any fire alarm signals from the System and line fault

2.2 Immediately upon receipt of fire alarm signals from the System to relay the fire alarm signal

2.3 Immediately upon receipt of fire alarm signal from System to notify the Appropriate Authority

2.4 To record details of fire alarm activation and line fault

3. SYSTEM TEST

3.1 Notify telcom company of any faults in the line which the company may discover

3.2 Request telcom company to make any necessary repairs on any line faults

4. REPORTS

4.1 To submit 2 reports to the Town Council for every activation

4.2 One from the Contractor and the other from the DECAM sub-con

5. CLAIMS

5.1a Town Council shall indemnify the Company against any claim

5.1b Made against the Contractor by the appropriate Authority

5.1b(1) A Defect in the Equipment

5.1b(2) Malfunction of the Equipment

5.1b(3) Improper installation or maintenance of the Equipment

5.1b(4) Smoke/heat from a burning source is a potential fire hazard

5.1b(5) To the premises or the contents therein

5.1b(6) An Act of God

5.1c By the Appropriate Authority due to a false alarm signal from System unless is attributed to.

Block No :

[illegible]

REMARKS

Name & signature of Technician(s)

1 *Silva*

2 _____

Verified By :

(Name & signature)