

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL

NEE SOON TOWN COUNCIL

LOCATION

NEE SOON LINK DIVISION

DATE OF SERVICING

29 /09/2025

MONTHLY HOSEREEL SYSTEM CHECKLIST REPORT

1. HOSEREEL

- 1.1 Check hosereels remain unobstructed
- 1.2 Ensure hosereel are available for use at all times
- 1.3 Check hosereel cabinet, hosereel and rubber hose for damage
- 1.4 Inspect the stop valves, glands, pipings and shut-off nozzles are free from leak
- 1.5 Check & verify operation of stop valve at hosereel pipe & ensure valve is fully closed
- 1.6 Check operation of nozzle and stopcock for blockage

Block No :

471A	471B	472A	472B	473A	473B
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/

REMARKS

Name & signature of Technician(s)

Verified By :

1 Selva Selva

(Name & signature)

2 _____

Blk 471B #1 1-2
Nozzle Box Glass
Broken need to
replace



NSL
Hosereel drum

IN CASE OF EMERGENCY,
BREAK GLASS TO OPEN DOOR


10:40 Sat
20/09/2025

- Work Content: glass missing & broken
- Forest Spring @ Yishun,
471B Yishun Street 42,
761471

Timemark App
Authentic time, GPS

Blk 472B #1 Nozzle
Box Glass Broken
need to replace

HOSEREEL NOZZLE BOX



IN CASE OF EMERGENCY,
BREAK GLASS TO OPEN DOOR



NSL
Hosereel drum

11:38 Sat
20/09/2025

- Work Content: glass missing & broken
- Forest Spring @ Yishun, 472B Yishun Street 42, 762472

Timemark App
Authentic time, GPS

Blk 471B #1 1-2
Nozzle Box Glass
Broken need to
replace



NSL
Hosereel drum

10:40 Sat
20/09/2025

- Work Content: glass missing & broken
- Forest Spring @ Yishun,
471B Yishun Street 42,
761471

Timemark App
Authentic time, GPS