

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL

NEE SOON TOWN COUNCIL

LOCATION

NEE SOON LINK DIVISION

DATE OF SERVICING

29. '09/2025

MONTHLY HOSEREEL SYSTEM CHECKLIST REPORT

1. HOSEREEL

- 1.1 Check hosereels remain unobstructed
- 1.2 Ensure hosereel are available for use at all times
- 1.3 Check hosereel cabinet, hosereel and rubber hose for damage
- 1.4 Inspect the stop valves, glands, pipings and shut-off nozzles are free from leak
- 1.5 Check & verify operation of stop valve at hosereel pipe & ensure valve is fully closed
- 1.6 Check operation of nozzle and stopcock for blockage

Block No :

477A	477B	477C	478	478A	478B
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/

REMARKS

Name & signature of Technician(s)


Verified By :

1 Selva Sg

(Name & signature)

2 _____

Blk 478 MSCP level- 1
glass broken



NSTC

Hosereel drum

11:19

Sun

21/09/2025

- Valley Spring @ Yishun, 478
Yishun Street 42, 760478
- Missing and broken glass

Timemark App
Authentic time, GPS

**Blk 478A level- 13 glass
broken**



NSTC

Hosereel drum

16:01


Sat

20/09/2025

- 478A Yishun Street 44
- Missing and broken glass

Timemark App
Authentic time, GPS

**Blk 478B level- 1 glass
broken**



NSTC

Hosereel drum

11:17


Sun

21/09/2025

- 478B Yishun Street 44
- Missing and broken glass

Timemark App
Authentic time, GPS

BIK 478B #3 1-2
Nozzle Box Glass
Broken need to
replace



NSL
Hosereel drum

16:23 Sat
20/09/2025

- Work Content: glass missing & broken
- Valley Spring @ Yishun, 478B
Yishun Street 44, 762478

Timemark App
Authentic time, GPS

BIK 478B #1 1-2
hosereel door can't
open

FIRE HOSE REEL
Turn on the inlet valve before running out the hose

IMPORTANT REMINDER



NSL
Hosereel drum

16:25 Sat
20/09/2025

- **Work Content: Door can't open**
- **Valley Spring @ Yishun, 478B**
Yishun Street 44, 762478

Timemark App
Authentic time, GPS

Blk 478B #9 1-2
Nozzle Box Glass
Broken need to
replace

HOSEREEL NOZZLE BOX

IN CASE OF EMERGENCY,
BREAK GLASS TO OPEN DOOR



NSL

Hosereel drum

16:19


Sat

20/09/2025

- Work Content: glass missing & broken
- Valley Spring @ Yishun, 478B
Yishun Street 44, 762478

Timemark App
Authentic time, GPS

Blk 478B #14 1-2
Nozzle Box Glass
Broken need to
replace



NSL
Hosereel drum


16:11 Sat
20/09/2025

- Work Content: glass missing & broken
- Valley Spring @ Yishun, 478B
Yishun Street 44, 762478

Timemark App
Authentic time, GPS

Blk 478B #12 1-2
Nozzle Box Glass
Broken need to
replace

HOSEREEL NOZZLE BOX



NSL

Hosereel drum

16:15

Sat

20/09/2025

- Work Content: glass missing & broken
- Valley Spring @ Yishun, 478B
Yishun Street 44, 762478

Timemark App
Authentic time, GPS