


Blk 454 HP alarm bell

Spoil



NSL

Hosereel pump

10:44 Tues
30/09/2025

- Work Content: spoil need to replace
- 454 Yishun Street 41

Timemark App
Authentic time, GPS

OT SWITCH OFF




HOSEREEL PUMP

MAIN INCOMING LIGHT



PUMP NO: 1 PUMP NO: 2



PUMP NO: 1 PUMP NO: 2



ALARM CANCEL LOW LEVEL LOW PRESSURE LAMP & BELL TEST



NSL

Hosereel pump

10:43 Tues
30/09/2025

- Work Content: spoil need to replace
- 454 Yishun Street 41

Timemark App
Authentic time, GPS

R111HBUGW24HXDE Timemark Verified

Blk 455 HP timer

Spoil



NSL
Hosereel pump

10:52 Tues
30/09/2025

- Work Content: spoil need to replace
- Blk 455 Yishun Street 41

Timemark App
Authentic time, GPS