

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

TOWN COUNCIL NEE SOON TOWN COUNCIL

LOCATION NEE SOON CENTRAL DIVISION

DATE OF SERVICING 28 /09/2025

1. QUALIFIED PERSON
 - 1.1 All servicing and recharging of fire extinguishers shall only be performed by qualified person
 - 1.2 Qualified person must belong to companies approved by Singapore Civil Defence Force
 - 1.3 Carry out maintenance as specified in CP 55: 1991
2. FIRE EXTINGUISHERS
 - 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
 - 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
 - 2.2 All fire extinguishers have not been discharged or lost pressure
 - 2.3 Access to and visibility of each extinguishers is not obstructed
 - 2.4 Operating instructions on each extinguishers surface shall be legible and faced outward
 - 2.5 Pressure gauge readings if any shall be in the operable range
 - 2.6 Any seals, safety clip or tamper indicators that are broken or missing shall be replaced
 - 2.7 Any physical damage, corrosion, leakage or clogged nozzle shall be rectified
 - 2.8 Damaged, broken or rusty fire extinguishers shall be repaired or replaced
 - 2.9 Keep inspection records for those extinguishers that are found to require corrective actions
 - 2.10 Submit inspection records to Superintending Officer
 - 2.11 All extinguishers are to be properly hung
 - 2.12 Date of service is shown and has not expired
 - 2.13 The extinguishers shall bear a PSB label

[illegible]

REMARKS
B4K-723-Switch Room - Fire Extinguishers need to top up.

1 Selva G

2 _____

(Name & signature)

Aug 20, 2025, 15:21


Blk 717 Lift B fire
extinguisher Dry
powder no have
need to top up



NSC
fire extinguisher

09:47 Fri
26/09/2025

- Work Content: missing & need to replace
- 2 Yishun Street 71, Blk 717 #01-321




Timemark App
Authentic time, GPS

YGTIPDG6G3MELAB Timemark Verified

Oct 03, 2024, 11:28

Blk 718 Lift C fire
extinguisher Dry
powder no have
need to top up



NSC
fire extinguisher

10:05 Fri
26/09/2025

- Work Content: missing & need to replace
- 718 Yishun Street 71, 760718

Timemark App
Authentic time, GPS

LL66G3A4NR1RLN Timemark Verified

Aug 20, 2025, 15:21

**Blk 720 Lift C fire
extinguisher missing
need to replace**



**NSC
fire extinguisher**

10:30 Fri
26/09/2025

- Work Content:missing & need to replace
- 721 Yishun Street 71,
760721

Timemark App
Authentic time, GPS

PM1P1PB3UYH3UU Timemark Verified

**Blk 723 switch room 1
fire extinguisher need to
top up**



Oct 03, 2024, 11:28

Blk 723 Lift B fire
extinguisher Dry
powder no have
need to top up



NSC
fire extinguisher

10:51 Fri
26/09/2025

- Work Content: missing & need to replace
- 723 Yishun Street 71, 760723



Timemark App
Authentic time, GPS

ERUYGD922EY4PY Timemark Verified

Aug 20, 2025, 15:21

**Blk 724 Lift B fire
extinguisher missing
need to replace**



**NSC
fire extinguisher**

11:08 Fri
26/09/2025

- Work Content: missing & need to replace
- 724 Yishun Street 71, 760724

Timemark App
Authentic time, GPS

© GXBATEH1U9L3AN Timemark Verified