

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

NEE SOON TOWN COUNCIL

CHONG PANG DIVISION

/09/2025

1. SIMULATED TEST
 - 1.1 Carry out a stimulated fire alarm call
 - 1.2 Operate any Alarm Zone
 - 1.3 Transmit a Fire Alarm Signal to the monitoring station and reset the system
 - 1.4 Simulate fire conditions on all alarm zones and reset the system to normal
 - 1.5 Disconnect battery and ensure visual & audible fault signals activated at main alarm panel
 - 1.6 Simulate main power failure and ensure system operate correctly with the standby battery power
 - 1.7 Simulate the fire alarm conditions and check the output signals availability
 - 1.8 Remote ancillary function is initiated during the fire alarm condition simulation test
 - 1.9 Simulate fault condition on all alarm zones to ensure main alarm panel is operating correctly
2. MONITORING STATION
 - 2.1 Contact the monitoring system prior to the transmitting of the fire alarm signal
 - 2.2 To warn them of the simulated fire condition to be tested
 - 2.3 Check & confirm with them after completion of test to ensure the fire alarm signal was received
 - 2.4 Advise the monitoring station that the system has been reset
 - 2.5 Notify them of intention to test and shut down the fire alarm system if applicable
3. BATTERY CONDITION
 - 3.1 Check the battery voltage in accordance with the manufacturer's instructions
 - 3.2 Check the battery conditions
 - 3.3 Check battery charging current in accordance with the manufacturer's instructions
 - 3.4 Check batteries and their terminals as specified by the manufacturer
 - 3.5 Ensure batteries and their terminals are in good servicable condition
 - 3.6 Examine to ensure that the specific gravity in each cell is correct
 - 3.7 Examine to ensure the level of the electrolyte in each cell is correct
 - 3.8 Check condition of battery cabinet for corrosion
 - 3.9 Ensure that batteries are stored in a secure condition
4. INDICATING LIGHTS
 - 4.1 Ensure that all indicating lights are operating correctly
 - 4.2 Replace any faulty indicating lights if any
5. SOUNDS
 - 5.1 Check operation of all alarm sounders
6. MAIN ALARM SYSTEM
 - 6.1 Check the main alarm panel is in a clean and operative condition
 - 6.2 Visually inspect the condition of components, terminations and cables
 - 6.3 Ensure that faulty parts are replaced
 - 6.4 Ensure that replacement has been carried out satisfactorily
7. SWITCHES
 - 7.1 Ensure that all switches are in the correct operating condition after completion of tests
 - 7.2 Take immediate steps to rectify the fault(s) should they exist
8. SMOKE DETECTORS
 - 8.1 Clean all smoke detectors every four months
9. DEFECTS
 - 9.1 Record in the log any fault(s) identified and that the above test has been carried out


[illegible]

Verified By :

1

2

(Name & signature)



RED POWER
R.V.RAM


11:19

Wed
10/09/2025

105 Yishun Ring Rd

Timemark App
Authentic time, GPS

© MPDLGB9EE6ED4K Timemark Verified



RED POWER
R.V.RAM

11:25 Wed
10/09/2025


■ 105 Yishun Ring Rd

Timemark App
Authentic time, GPS

2 _____

2 _____

BUK-104 (Mandel) Fire Extinguisher need to toy up.



RED POWER
DURAI

13:42 Wed
10/09/2025

107 Yishun Ring Rd

Timemark App
Authentic time, GPS



© 13GN39URMTNTEN Timemark Verified



RED POWER
DURAI

10:51 Wed
10/09/2025

■ 109 Yishun Ring Road,
760109

Timemark App
Authentic time, GPS



RED POWER
DURAI

10:51

Wed
10/09/2025

109 Yishun Ring Road,
760109

Timemark App
Authentic time, GPS



RED POWER
DURAI

10:52 Wed
10/09/2025

■ 109 Yishun Ring Road,
760109



Timemark App
Authentic time, GPS



RED POWER
DURAI

10:53 Wed
10/09/2025

109 Yishun Ring Road,
760109

Timemark App
Authentic time, GPS

© 1GRL3XMLXWRHM3 Timemark Verified

(Name & signature)

**Blk 113 switch room 2 fire
extinguisher missing**



**RED POWER
DURAI**

15:37 Wed
10/09/2025

■ 113 Yishun Ring Road,
760113

Timemark App
Authentic time, GPS

(Name & signature)

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

NEE SOON TOWN COUNCIL

CHONG PANG DIVISION

/09/2025

1. QUALIFIED PERSON
- 1.1 All servicing and recharging of fire extinguishers shall only be performed by qualified person
- 1.2 Qualified person must belong to companies approved by Singapore Civil Defence Force
- 1.3 Carry out maintenance as specified in CP 55: 1991
2. FIRE EXTINGUISHERS
- 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
- 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
- 2.2 All fire extinguishers have not been discharged or lost pressure
- 2.3 Access to and visibility of each extinguishers is not obstructed
- 2.4 Operating instructions on each extinguishers surface shall be legible and faced outward
- 2.5 Pressure gauge readings if any shall be in the operable range
- 2.6 Any seals, safety clip or tamper indicators that are broken or missing shall be replaced
- 2.7 Any physical damage, corrosion, leakage or clogged nozzle shall be rectified
- 2.8 Damaged, broken or rusty fire extinguishers shall be repaired or replaced
- 2.9 Keep inspection records for those extinguishers that are found to require corrective actions
- 2.10 Submit inspection records to Superintending Officer
- 2.11 All extinguishers are to be properly hung
- 2.12 Date of service is shown and has not expired
- 2.13 The extinguishers shall bear a PSB label

Block No :							
123	124	125	126	127	128	129	130
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							
							

Verified By :

1 Selva of

2

(Name & signature)

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

NEE SOON TOWN COUNCIL

CHONG PANG DIVISION

2 /09/2025

1. QUALIFIED PERSON

- 1.1 All servicing and recharging of fire extinguishers shall only be performed by qualified person
- 1.2 Qualified person must belong to companies approved by Singapore Civil Defence Force
- 1.3 Carry out maintenance as specified in CP 55: 1991
2. FIRE EXTINGUISHERS
 - 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
 - 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
 - 2.2 All fire extinguishers have not been discharged or lost pressure
 - 2.3 Access to and visibility of each extinguishers is not obstructed
 - 2.4 Operating instructions on each extinguishers surface shall be legible and faced outward
 - 2.5 Pressure gauge readings if any shall be in the operable range
 - 2.6 Any seals, safety clip or tamper indicators that are broken or missing shall be replaced
 - 2.7 Any physical damage, corrosion, leakage or clogged nozzle shall be rectified
 - 2.8 Damaged, broken or rusty fire extinguishers shall be repaired or replaced
 - 2.9 Keep inspection records for those extinguishers that are found to require corrective actions
 - 2.10 Submit inspection records to Superintending Officer
 - 2.11 All extinguishers are to be properly hung
 - 2.12 Date of service is shown and has not expired
 - 2.13 The extinguishers shall bear a PSB label

139	140	141	142	143	144	145	146

REMARKS

Name & signature of Technician(s)

Verified By :

1 Solva by

2

(Name & signature)

(Name & signature)

**Blk 153 lift room fire
extinguisher need to top
up**



**RED POWER
DURAI**


15:40 Mon
15/09/2025

■ 153 Yishun Street 21

Timemark App
Authentic time, GPS

(Name & signature)

**Blk 162 RHE fire
extinguisher missing**



**RED POWER
DURAI**

10:26 Sat
13/09/2025

■ Bakkar Turkish Kebab, 162
Yishun Street 11, #08-270,
760162

Timemark App
Authentic time, GPS

(Name & signature)

**Blk 165 court, fire
extinguisher key glass
broken need to replace**

FIRE EXTINGUISHER



**RED POWER
DURAI**

10:19 Tues
16/09/2025

■ 165 Yishun Ring Rd

Timemark App
Authentic time, GPS

**Blk 165 court, fire
extinguisher , ABC dry
powder need to top up**



**RED POWER
DURAI**

10:13 Tues
16/09/2025

■ BlueSG, 165 Yishun Ring
Road, 760165

Timemark App
Authentic time, GPS

**Blk 165 court, fire
extinguisher ABC dry
powder need to top up**



**RED POWER
DURAI**

10:13 Tues
16/09/2025

■ BlueSG, 165 Yishun Ring
Road, 760165

Timemark App
Authentic time, GPS

**Blk 165 court, fire
extinguisher ABC dry
powder need to top up**



**RED POWER
DURAI**

10:18 Tues
16/09/2025

■ 165 Yishun Ring Rd

Timemark App
Authentic time, GPS

**Blk 165 court, fire
extinguisher ABC dry
powder need to top up**

**Fire extinguisher head
missing need to replace**



**RED POWER
DURAI**

10:14 Tues
16/09/2025

■ BlueSG, 165 Yishun Ring
Road, 760165

Timemark App
Authentic time, GPS

(Name & signature)



NSTC

fire extinguisher

10:08 Fri
19/09/2025

■ 269A Yishun Street 22,
761269

■ fire extinguisher missing

Timemark App
Authentic time, GPS



NSTC

fire extinguisher

10:09 Fri
19/09/2025

- 269B Yishun Street 22,
762269
- fire extinguisher missing



© MNLPH412UCKMWA Timemark Verified

Timemark App
Authentic time, GPS



NSTC

fire extinguisher

10:09

Fri

19/09/2025

■ 269B Yishun Street 22,
762269

■ fire extinguisher missing



© MNLPH412UCKMWA Timemark Verified

Timemark App
Authentic time, GPS



NSTC

fire extinguisher

10:08 Fri
19/09/2025

■ 269A Yishun Street 22,
761269

■ fire extinguisher missing

Timemark App
Authentic time, GPS



NSTC

fire extinguisher

10:08 Fri
19/09/2025

■ 269A Yishun Street 22,
761269

■ fire extinguisher missing

Timemark App
Authentic time, GPS



NSTC

fire extinguisher

10:09

Fri

19/09/2025

- 269B Yishun Street 22,
762269
- fire extinguisher missing



© MNLPH412UCKMWA Timemark Verified

Timemark App
Authentic time, GPS

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

LOCATION CHONG PANG DIVISION

DATE OF SERVICING 3 /09/2025

1. QUALIFIED PERSON
- 1.1 All servicing and recharging of fire extinguishers shall only be performed by qualified person
- 1.2 Qualified person must belong to companies approved by Singapore Civil Defence Force
- 1.3 Carry out maintenance as specified in CP 55: 1991
2. FIRE EXTINGUISHERS
- 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
- 2.1 All fire extinguishers are in their designated & proper places as specified by code of practice
- 2.2 All fire extinguishers have not been discharged or lost pressure
- 2.3 Access to and visibility of each extinguishers is not obstructed
- 2.4 Operating instructions on each extinguishers surface shall be legible and faced outward
- 2.5 Pressure gauge readings if any shall be in the operable range
- 2.6 Any seals, safety clip or tamper indicators that are broken or missing shall be replaced
- 2.7 Any physical damage, corrosion, leakage or clogged nozzle shall be rectified
- 2.8 Damaged, broken or rusty fire extinguishers shall be repaired or replaced
- 2.9 Keep inspection records for those extinguishers that are found to require corrective actions
- 2.10 Submit inspection records to Superintending Officer
- 2.11 All extinguishers are to be properly hung
- 2.12 Date of service is shown and has not expired
- 2.13 The extinguishers shall bear a PSB label

[illegible]

REMARKS

Name & signature of Technician(s)

1 Selma Sel.

2

Verified By :

(Name & signature)

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197
TEL : 6 289 2298 FAX : 6 287 9635

NEE SOON TOWN COUNCIL

CHONG PANG DIVISION

2/09/2025

1. GENERAL

1.1a If any part of DECAM equipment supplied by DECAM sub-con become defective/repairs required

1.1b Contractor shall carry out all the repairs and replacement of parts at its own expense

2. ALARM

2.1 Monitor the Premises 24 hours daily for any fire alarm signals from the System and line fault

2.2 Immediately upon receipt of fire alarm signals from the System to relay the fire alarm signal

2.3 Immediately upon receipt of fire alarm signal from System to notify the Appropriate Authority

2.4 To record details of fire alarm activation and line fault

3. SYSTEM TEST

3.1 Notify telcom company of any faults in the line which the company may discover

3.2 Request telcom company to make any necessary repairs on any line faults

4. REPORTS

4.1 To submit 2 reports to the Town Council for every activation

4.2 One from the Contractor and the other from the DECAM sub-con

5. CLAIMS

5.1a Town Council shall indemnify the Company against any claim

5.1b Made against the Contractor by the appropriate Authority

5.1b(1) A Defect in the Equipment

5.1b(2) Malfunction of the Equipment

5.1b(3) Improper installation or maintenance of the Equipment

5.1b(4) Smoke/heat from a burning source is a potential fire hazard

5.1b(5) To the premises or the contents therein

5.1b(6) An Act of God

5.1c By the Appropriate Authority due to a false alarm signal from System unless is attributed to.

Block No :

[illegible]

REMARKS

Name & signature of Technician(s)

1 *Silva*

2 _____

Verified By :

(Name & signature)