

A-DASHBOARD




B-STATION




Device & Instruments	Device & Instruments For consolidation(stepped loading)/swelling/UCT
Cell Pressure Control Device1 Cell Pressure 0 kPa	Vertical Load Control Not Assigned Vertical Load N Displacement mm
Vertical Load Control Not Assigned Vertical Load Displacement Pore Water Pressure Wertical Load N N Displacement N KPa	
Device & Instruments For Shearbox	Device & Instruments Saturation(Incremental) / Isotropic Consolidation
Vertical Load Control Not Assigned Vertical Load Not Assigned Not Not Assigned Not	Cell Pressure Control Device1 Cell Pressure 0 kPa Back Pressure Control Device2 Back Pressure 0 kPa Volume Change 0 ml Pore Water Pressure 0 kPa
Device & Instruments For permeability Live reading	
Cell Pressure Control Device1 Cell Pressure 0 kPa	Device & Instruments For User defined Test
Back Pressure Control Device2 Back Pressure 0 kPa Inlet Volume Change 0 cm3 Pore Water Pressure 0 kPa Back Pressure 2 Control Device3 Back Pressure 2 0 kPa Outlet Volume Change 0 cm3	Cell Pressure Control Device1


C-STATION NAME




D-DEVICES




E- ADD NEW DEVICE




F-DEVICE CONTROL PANEL




H-CREATE TEST




I-TEST PANEL






J-SAMPLE


K-ADD TEST





L-TEST PLAN TEMPLATE



M-RUN TEST









N-DATA VIEW

est Panel 1 : "test	xxx"		_ □ ×	
JobNo	Job Description	Sample ID		
Enter Text	Enter Text	Enter Text	Enter Text	
			Log	gged data
			in `	Table forn

O-TEST PLAN SELECT



P-JOB RECORD



Q-TEST PLAN TEMPLATE

Test Plan Template	e: Saturation				
			File Name: Enter Text		
Initial Conditions	Logging Conditions	Stopping Conditions			
			Арр	ly	