ELECTRONICS CHEAT SHEET

Mass

Torque

Capacity

Temperature

Rotational speed

IMPERIAL & METRIC CONVERSION

Millimeters x 0.03937 = inches Centimeters x 0.3937 = inches Meters x 3.281 = feet Kilometers x 0.6214 = miles

METRIC POWERS OF A THOUSAND

Amount	Multiplier	Prefix/Abbr
Trillion	1,000,000,000,000	tera- (T)
Billion	1,000,000,000	giga- (G)
Million	1,000,000	mega- (M)
Thousand	1,000	kilo- (k)
Thousandth	0.001	milli- (m)
Millionth	0.000001	micro- (µ/u)
Billionth	0.000000001	nano (n)
Trillionth	0.000000000001	pico (p)

MISSING UNITS

Type	<u>Units</u>
Battery	volts (V)
Large capacitor	microfarads (µF)
Small capacitor	picofarads (pF)
Crystal	megahertz (MHz)
Inductor	henrys (H)
Oscillator	megahertz (MHz)
Potentiometer	ohms (Ω)
Resistor	ohms (Ω)

Measurement Units Abbr Length meter m Resistance ohm Ω V Voltage volt Current ampere or amp Α Power W watt Frequency Hz hertz F Capacitance farad Inductance henry G Amplification beta factor h_{FE} or β Luminous intensity candela cd

gram

newton-meter

revolution per min

amp-hour

Calsius

g

Nm

Ah

°C

rpm

Unit Abbreviations

Color Band Values				
Color	1st Band	2nd Band	3rd Band	
Black	0	0	x1	
Brown	1	1	x10	
Red	2	2	x100	
Orange	3	3	x1,000	
Yellow	4	4	x10,000	
Green	5	5	x100,000	
Blue	6	6	x1,000,000	
Violet	7	7		
Gray	8	8		
White	9	9		

	Color Tolerance Bands
Color	Tolerance
(none)	20%
Silver	10%
Gold	5%
Red	2%
Brown	1%