## **Tyseley Depot Visitor and Contractor Safety Induction Brief**

## **Laurie Bower**

## **Date / Time Student Score Passing Score Result**

March 23, 2020

92

80

Pass

10:25 am

## **Tyseley Depot Visitor and Contractor Safety Induction Brief**

#	Question	<b>Correct Answer</b>	Student Answer	Result	<b>Points Awarded</b>
1	Click on the item that must be removed when exiting a train. If you have an accident	·	Hotspot 2	Correct	10
2	in the factory, who should you report to?	The Designated Person	The Designated Person	Correct	10
3	In miles per hour, what speed limit must be adhered to at all times within the depot and car parks? Click on the correct sign.	Oval Hotspot 1	Oval Hotspot 1	Correct	10
4	What must you do if a spillage occurs?	Initially attempt to contain the spill using the spill kit and advise West Midlands Trains DP of the incident	Initially attempt to contain the spill using the spill kit and advise West Midlands Trains DP of the incident	Correct	10
5	Where would you find first aid equipment. Which TWO locations are correct?	Fuel Pit:- Operating Team Leader's Office , Factory:- Team Manager's Office	Fuel Pit:- Operating Team Leader's Office , Factory:- Team Manager's Office	Correct	10
6	When crossing the railway line, you should walk on the ballast.	True	True	Correct	10
7	What is shown in the	The fire assembly	The fire assembly	Correct	10

picture? Which statement is	point	point		
correct? Click and drag the answer in to the empty space.	Mandatory signs are blue	Mandatory signs are blue	Correct	10
What does the acronym COSHH stand for?  If you need to use a	Control of Substances Hazardous to Health	Control of Substances Hazardous to Health	Correct	10
10 mobile phone where should you be?	In a position of safety	In a position of safety	Correct	10
11 Which statement is correct?	You must not work any longer than 12 hours per day	Use the pit bridge when necessary	Incorrect	0
What must you conform	The Henrydeus Wests			
12 to when removing hazardous waste from the site?	The Hazardous Waste Regulations	The COSHH Register	Incorrect	0
What must you do when crossing the track?	crossing the highway	Look both ways as if crossing the highway	Correct	10
Under what circumstances are you 14 allowed to bring chemicals onto the depot?	When they have been declared on the risk assessment and method statement and authorised by	declared on the risk assessment and method statement and authorised by	Correct	10
·	West Midlands Trains	West Midlands Trains		
If a spillage occurs, in 15 which colour bins are the spill kits located?	Yellow	Yellow	Correct	10
16 You can drink alcohol at lunch time.	False	False	Correct	10
What TWO additional 17 PPE must be worn when entering the pit?	Head protection, Eye Protection	Head protection, Eye Protection	Correct	10
If a driver sounds a 18 warning, what must you do?	Raise one arm above your head, and if necessary, move to a position of safety	Raise one arm above your head, and if necessary, move to a position of safety	Correct	10
Smoking is permitted 19 anywhere on Tyseley Depot.	False	False	Correct	10
A pit bridge is 20 considered to be part of a walking route.	False	False	Correct	10
On which day and at 21 what time is the Fire Alarm tested? Which TWO items of	Tuesday at 08.30	Tuesday at 08.30	Correct	10
personal protective equipment must  22 contractors and visitors wear when on the	Safety Footwear, High visibility clothing	Safety Footwear, High visibility clothing	Correct	10

depot?  If required to cross running lines with a road vehicle what must you ensure you do before commencing any movement?	Obtain permission from the Designated Person	Obtain permission from the Designated Person	Correct	10
When working in the Carriage sidings who must you gain 24 permission from before starting work? Click and drag the answer in to the empty space.	The person in charge of sidings	The person in charge of sidings	Correct	10
On a daily basis, what 25 must do when arriving at Tyseley Depot?	Sign in on arrival using the electronic sign-in monitor	Sign in on arrival using the electronic sign-in monitor	Correct	10