## **Tyseley Depot Visitor and Contractor Safety Induction Brief**

## **Dalwara Singh**

## **Date / Time Student Score Passing Score Result**

January 22, 2020

100

80

Pass

10:35 am

## **Tyseley Depot Visitor and Contractor Safety Induction Brief**

#	Question	Correct Answer	Student Answer	Result Points Awarded
1	Which statement is correct? Click and drag the answer in to the empty space.	Mandatory signs are blue	Mandatory signs are blue	Correct 10
2	If you have an accident in the factory, who should you report to?	The Designated Person	The Designated Person	Correct 10
3	If a spillage occurs, in which colour bins are the spill kits located?	Yellow	Yellow	Correct 10
4	Smoking is permitted anywhere on Tyseley Depot.	False	False	Correct 10
5	If a driver sounds a warning, what must you do?	Raise one arm above your head, and if necessary, move to a position of safety	Raise one arm above your head, and if necessary, move to a position of safety	Correct 10
6	Which statement is correct?	You must not work any longer than 12 hours per day	You must not work any longer than 12 hours per day	Correct 10
7	What is shown in the picture?	The fire assembly point	The fire assembly point	Correct 10
8	You can drink alcohol at lunch time.	False	False	Correct 10
	What must vou do if a	Initially attempt to contain the spill using	Initially attempt to contain the spill using	

9 spillage occurs?	the spill kit and advise London Midland DP of the incident	the spill kit and advise London Midland DP of the incident	Correct 10
On which day and at 10 what time is the Fire Alarm tested?	Tuesday at 08.30	Tuesday at 08.30	Correct 10
Click on the item that 11 must be removed when exiting a train. Which TWO items of personal protective	Hotspot 2	Hotspot 2	Correct 10
12 equipment must contractors and visitors wear when on the depot?	Safety Footwear, High visibility clothing	Safety Footwear, High visibility clothing	Correct 10
When crossing the 13 railway line, you should walk on the ballast.	True	True	Correct 10
When working in the Carriage sidings who must you gain 14 permission from before starting work? Click and drag the answer in to the empty space.	The person in charge of sidings	The person in charge of sidings	Correct 10
Where would you find first aid equipment. Which TWO locations are correct?	Fuel Pit:- Operating Team Leader's Office , Factory:- Team Manager's Office	Fuel Pit:- Operating Team Leader's Office , Factory:- Team Manager's Office	Correct 10
If required to cross running lines with a road vehicle what must you ensure you do before commencing any movement?	Obtain permission from the Designated Person	Obtain permission from the Designated Person	Correct 10
If you need to use a 17 mobile phone where should you be?	In a position of safety	In a position of safety	Correct 10
What does the acronym COSHH stand for?	Control of Substances Hazardous to Health	Control of Substances Hazardous to Health	Correct 10
A pit bridge is 19 considered to be part of a walking route.	False	False	Correct 10
Under what circumstances are you 20 allowed to bring chemicals onto the depot?	When they have been declared on the risk assessment and method statement and authorised by West Midlands Trains	When they have been declared on the risk assessment and method statement and authorised by West Midlands Trains	Correct 10
What TWO additional 21 PPE must be worn when		Head protection, Eye Protection	Correct 10

entering the pit? What must you conform to when removing The Hazardous Waste The Hazardous Waste Correct 10 hazardous waste from Regulations Regulations the site? On a daily basis, what Sign in on arrival Sign in on arrival using the electronic 23 must do when arriving at using the electronic Correct 10 Tyseley Depot? sign-in monitor sign-in monitor What must you do when Look both ways as if crossing the track? crossing the highway Look both ways as if Correct 10 crossing the highway crossing the highway In miles per hour, what speed limit must be adhered to at all times Oval Hotspot 1 Oval Hotspot 1 Correct 10 within the depot and car parks? Click on the correct sign.