
ENKU Base R142 | NO FAB


F.Cu - top copper



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R142 | NO FAB


In1.Cu - inner copper



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R142 | NO FAB


In2.Cu - inner copper



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R142 | NO FAB

B.Cu - bottom copper, unmirrored




Source 1ce355545d21d849e924... | native KiCad 10.0.7 | 4/10

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R142 | NO FAB

F.Mask - openings




Source 1ce355545d21d849e924... | native KiCad 10.0.7 | 5/10

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R142 | NO FAB

B.Mask - openings



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R142 | NO FAB


F.Paste - top stencil



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R142 | NO FAB


B.Paste - intentionally empty



No bottom paste apertures. Actual closed outline shown for orientation.

ENKU Base R142 | NO FAB

F.Fab - assembly and pad numbers




Source 1ce355545d21d849e924... | native KiCad 10.0.7 | 9/10

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R142 | NO FAB

B.Fab - service references



Source 1ce355545d21d849e924... | native KiCad 10.0.7 | 10/10

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.