
ENKU Base R143 | NO FAB


F.Cu - top copper



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R143 | NO FAB


In1.Cu - inner copper



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R143 | NO FAB

In2.Cu - inner copper




Source 3319ad4325e1856a9237... | native KiCad 10.0.7 | 3/10

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R143 | NO FAB

B.Cu - bottom copper, unmirrored



Source 3319ad4325e1856a9237... | native KiCad 10.0.7 | 4/10

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R143 | NO FAB

F.Mask - openings

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R143 | NO FAB

B.Mask - openings

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R143 | NO FAB


F.Paste - top stencil



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R143 | NO FAB


B.Paste - intentionally empty



No bottom paste apertures. Actual closed outline shown for orientation.

ENKU Base R143 | NO FAB


F.Fab - assembly and pad numbers



Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.

ENKU Base R143 | NO FAB

B.Fab - service references



Source 3319ad4325e1856a9237... | native KiCad 10.0.7 | 10/10

Unmirrored board coordinates. Engineering view; use paired Gerber/drill data for CAM.