OBD2 Fault Codes Reference

P0121 - Throttle Position Sensor/Switch A Circuit Range/Performance Problem B1601 - PATS Received Incorrect Key-Code From Ignition Key Transponder C1400 - Traction Control Valve RF Circuit Failure U1040 - SCP (J1850) Invalid or Missing Data for Vehicle Speed

P0219 - Engine Overspeed Condition P1870 - Transmission Component Slipping P0562 - System Voltage Low P0562 - A/C pressure sensor low voltage (Chrysler)

P0036 - H02S Heater Control Circuit (Bank 1 Sensor 2) P0037 - H02S Heater Control Circuit Low (Bank 1 Sensor 2) P0038 - H02S Heater Control Circuit High (Bank 1 Sensor 2)

P0307 - Cylinder 7 Misfire Detected P0279 - Cylinder 7 Injector Circuit Low

B9999 - Created in XML format by Sinclair Easton

This document contains OBD2 diagnostic trouble codes and their descriptions.