QQ Plots Calibration A Sensor 1 Sensor 3 Sensor 2 50 50 40 40 40 Ordered Values Ordered Values Ordered Values 30 30 20 20 10 10 0 0 0 -10 -10 -2 2 -2 2 -2 2 -4 4 0 -4 Theoretical quantiles Theoretical quantiles Theoretical quantiles Sensor 4 Sensor 5 1.0 40 40 30 8.0 30 Ordered Values Ordered Values 20 0.6 20 10 10 0.4 0 0 0.2 -10 -10 0.0 2 -2 2 0.0 0.2 0.4 0.6 8.0 -4 4 0 4 1.0

Theoretical quantiles

Theoretical quantiles