Only a little cotton candy is produced during the sugar making process, and there are flying strands



Solution

The temperature of the furnace is too high. Enter the management background, click the parameter setting and adjust the sugar temperature of the furnace head lower by 5 degrees.

Created by



Jason Lopez