Wiring Set and Mounting Plate



Mount with 4 nuts to hold in place.



Plug in main cable and antenna cable.



Make sure to connect cable that says "Com 2" not Com 1.



Connect Com 2 to machine Serial port and the power to power as shown.



Located here are the power and comm peripheral connections.

