
Connectivity and User Interface



Example interface



25–35 °C

500–1500 RPM

pH 3–7

Monitor readings and trends.


Adjust temperature, speed and pH.

Log data and export CSV.

Connectivity and User Interface



Example interface



25–35 °C

500–1500 RPM

pH 3–7


Monitor readings and trends.

Adjust temperature, speed and pH.

Log data and export CSV.

Command flow and software structure

Command flow



An applied target is confirmed by the control board. Reaching that target takes longer.

Software structure

