TORQUE STRIPE

FAA proposed AD applicability report

Report 2F12BD5B7C3C
2026-10-31 06:08:08 UTC

QUESTION

Aircraft / engine model	AS350B3
Question	main rotor servo-control torque inspection
Dataset	431 FAA NPRM notices, 323 dockets, 1,302 Federal Register pages · as of 2026-10-31

ANSWERED

Proposed for all AS350B3 units

The model is listed and the notice says the proposal applies to all units.

RULE CHECKS (DETERMINISTIC)

Check	Detail	Result
Docket identified	FAA-2026-11814	Nominal
Latest version used	1 version, newest 2026-10-19	Nominal
Regulatory status	Proposed, not binding	Proposed
Model listed	All units covered	Nominal
Evidence quoted	3 sentences, word for word	Nominal

PROPOSAL

Docket	FAA-2026-11814
Regulatory status	Proposed · not binding
Binding	No. This is a proposed rule (NPRM), not an AD in force.
Comments due	2026-12-03 (open)
Make	Airbus Helicopters
Scope wording	All units of listed models
Applicability	AS350B3 matches listed model AS350B3. Summary says the proposal applies to ALL units of the listed models.
Latest publication	Federal Register, Volume 91 Number 200 (Monday, October 19, 2026) (Pages 66019-66022)

VERSION HISTORY

Date	Action	Federal Register	Sheet row
2026-10-19	new ad	Federal Register, Volume 91 Number 200 (Monday, October 19, 2026) (Pages 66019-66022)	2

EVIDENCE, QUOTED WORD FOR WORD

> “The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Helicopters Model AS350B3, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters.”
>
> S1 · FAA-2026-11814 · 2026-10-19 · new ad · Federal Register, Volume 91 Number 200 (Monday, October 19, 2026) (Pages 66019-66022) · sheet row 2
> https://www.federalregister.gov/documents/2026/10/19/2026-21387/airworthiness-directives-airbus-helicopters

> “This proposed AD would require an inspection of the nut tightening torque of the upper ball bearing end of all the MR servo-controls and, depending on the results, corrective actions.”
>
> S3 · FAA-2026-11814 · 2026-10-19 · new ad · Federal Register, Volume 91 Number 200 (Monday, October 19, 2026) (Pages 66019-66022) · sheet row 2
> https://www.federalregister.gov/documents/2026/10/19/2026-21387/airworthiness-directives-airbus-helicopters

> “The proposed AD would also require reporting the inspection results.”
>
> S4 · FAA-2026-11814 · 2026-10-19 · new ad · Federal Register, Volume 91 Number 200 (Monday, October 19, 2026) (Pages 66019-66022) · sheet row 2
> https://www.federalregister.gov/documents/2026/10/19/2026-21387/airworthiness-directives-airbus-helicopters

No AI rewording: sentences are quoted directly from the notice.

RULE TRACE

```
1. intent=requirements model=AS350B3 serial=null topic=[main, rotor, servo-control, torque, inspection]
2. model AS350B3 listed in 29 dockets
3. topic coverage=1.00
4. ranked FAA-2026-11814:18.8, FAA-2026-7231:8.6, 97-ANE-59-AD:5.7, 2002-CE-27-AD-W:5.5, FAA-2004-19930:3.2
5. docket FAA-2026-11814: 1 version(s); status PROPOSED
6. applicability=MODEL_LISTED_ALL_UNITS: AS350B3 matches listed model AS350B3. | Summary says the proposal applies to ALL units of the listed models.
```

LIMITATIONS

- These are proposed rules (NPRMs), not airworthiness directives in force. Withdrawn proposals impose no requirement.
- Where the notice covers "certain" units, serial-number or configuration criteria are only in the full Federal Register text and were not confirmed here.
- Status, applicability and refusals are decided by deterministic rules over the dataset named above. Check the cited Federal Register pages before acting.

ENGINEER REVIEW

☐ Accepted ☐ Not applicable to our fleet ☐ Further review required

Name _____ Licence / authorisation number _____

Signature _____ Date _____

SHA-256
2f12bd5b7c3c007eb0b8bb919d407befc44d16b4aaa1d98906474413b579ca99