

# Concrete Floor Degreaser - Heavy-Duty Alkaline

Heavy-Duty Alkaline Degreaser with Deep-Penetrating Surfactant System + Solvent Boost Concrete & Industrial Floor Care for factory floors, warehouses & heavy machinery bays

## 01 Document control

### DOCUMENT ID

ACX-SOP-ACXCONCDEGVAR

### STATUS

Professional facility use

### MARKET

India

### SOURCE BASIS

Current Alle's ClinX product catalogue + current public SDS

## 02 Control requirement

Use with the current label, SDS, technical instructions and site-specific controls.

## 03 Purpose

Define a repeatable, supervised and documented method for professional use of Concrete Floor Degreaser - Heavy-Duty Alkaline, including preparation, PPE, dose/dilution, application, verification, incident response and storage.

# Scope, roles and stop-work authority

Defines who may use the product, what each role controls, and when work must stop.

## 01 Scope

Heavy-Duty Alkaline Degreaser with Deep-Penetrating Surfactant System + Solvent Boost Concrete & Industrial Floor Care for factory floors, warehouses & heavy machinery bays

## 02 Roles

### Supervisor / facility lead

### Operator

Approve task fit, confirm current controlled Follow dose/dilution and sequence exactly; use documents, ensure PPE/access controls and PPE; stop work when conditions fall outside the review deviations. SOP.

### EHS / technical reviewer

### Procurement / stores

Resolve uncertain compatibility, exposure, Maintain labelled stock, correct segregation, incident or formulation questions before work current revision documents and traceable resumes. product identity.

## 03 Stop-work authority

- Any uncontrolled splash, acid/alkali cross-contact or loss of corrosive-duty PPE.
- Unexpected reaction, heat, fumes, odour or visible surface attack.
- Damaged or unlabelled container, uncertain product identity or uncertain compatibility.
- Splash/exposure event or uncontrolled spill.

# Hazard controls before product handling

Use the current SDS classification and task risk assessment; product appearance or fragrance is not a safety control.

## 01 Current SDS hazard profile



### DANGER GHS05

H314 - Causes severe skin burns and eye damage.

## 02 PPE selection



Protective gloves



Eye protection



Face shield where splash risk is significant



Respiratory protection only where site risk

## 03 Primary failure modes

### 01 Corrosive exposure

Prevent skin/eye contact; control splashes; use gloves and eye/face protection.

### 02 Surface attack

Confirm compatibility and do not exceed stated strength/contact conditions.

### 03 Wrong dilution / dose

Measure product; do not free-pour where a defined dilution or dose is specified.

### 04 Incompatible chemistry

Never mix cleaning chemicals unless current controlled documentation explicitly permits it.

# Pre-use checklist

No application begins until product identity, compatibility, area controls, PPE and cleanup resources are confirmed.

01

**Read current SDS**

Confirm current label/SDS and site procedure before use.

02

**Confirm application**

Use only for the intended task, surface, equipment or hygiene purpose.

03

**Prepare the area**

Control access, remove incompatible products and arrange ventilation where needed.

04

**Wear corrosive-duty PPE**

Chemical-resistant gloves and eye/face protection are mandatory for concentrate handling.

05

**Prepare rinse / cleanup**

Have water, wipes or approved cleanup materials ready before starting.

01

## Product setup

**DOSE / DILUTION**

1:5 to 1:20 depending on soil level

**APPLICATION**

Mop, scrubber-dryer, or pressure washer

**RINSE / FINISH**

Yes - rinse or wet-vacuum after dwell time

# Step-by-step operating procedure

1:5 to 1:20 depending on soil level | Mop, scrubber-dryer, or pressure washer

## Prepare

01

Read the current label/SDS, confirm compatibility, isolate the task area and prepare PPE.

## Dilute

02

1:10 to 1:20 in water for routine cleaning; use neat or at 1:5 for heavily soiled or long-neglected areas.

## Apply & agitate

03

apply with mop, scrubber-dryer or pressure washer, allow 5-10 minutes dwell time on heavy soiling, agitate, then rinse or wet-vacuum thoroughly.

## Rinse / finish

04

Yes - rinse or wet-vacuum after dwell time

## Verify

05

Confirm the required result, correct finish and safe condition before closing the task.

## Close out

06

Reseal and return the product to storage, restore the work area and report any abnormal result or deviation.

# Quality verification and task release

Application alone is not completion; verify the result and confirm the area is safe to return to service.

## 01 Completion criteria

- Required soil / contamination / hygiene task has been addressed to the facility standard.
- No visible chemical residue remains where the process requires rinsing or wipe-off.
- No material damage, discolouration, etching, swelling or finish change is visible.
- Area, equipment or item is safe to return to service.
- Container is closed, labelled and returned to the correct storage location.
- Any deviation, repeat cycle, spill, exposure or damage is recorded and escalated.

## 02 Process data to record

### Date / location

### Product / batch

Where and when the task occurred. Product identity and batch/lot where available.

### Dose / dilution

### Operator / supervisor

Actual measured amount or working dilution. Who performed and who released the task.

### Deviation / incident

Any repeat, damage, spill, exposure or unusual result.

# Surface, material and equipment compatibility

Identify the material before application. Compatibility failures are preventable when limits are checked first.

## 01 Compatibility matrix

### Compatible after check

- Compatible hard floors listed in product literature

### Verify before use

- Aluminium / alkali-sensitive finishes unless confirmed
- Unknown surfaces without spot testing

## 02 Use-case boundaries

01 Supports consistent professional facility use when applied according to the current product instructions.

02 Provides alkaline cleaning action for the stated soil and professional application range.

03 Supports the stated professional application method when dosing and equipment controls are followed.

04 Supports removal of greasy soil that can contribute to unsafe floor conditions.

# Exposure, spill and abnormal reaction

Stop the task, protect people first, then contain and escalate according to the current SDS and site emergency procedure.

## 01 First aid

### Eyes

ACT IMMEDIATELY. Flush eyes with clean water for a minimum of 15 minutes, holding eyelids open and rolling eyes to ensure full irrigation. Remove contact lenses if present and easy to do - continue rinsing. Seek immediate medical/ophthalmological attention even if no symptoms are present.

### Skin

Immediately remove contaminated clothing including shoes. Flush affected skin with large amounts of water for at least 15 minutes. Do not scrub. Apply soap if available after initial rinsing. If irritation, redness, or pain persists, seek medical attention. Wash clothing before reuse.

### Inhalation

Remove affected person to fresh air immediately. If breathing is difficult, administer oxygen. If breathing has stopped, apply artificial respiration. Keep person warm and at rest. Seek medical attention if symptoms (coughing, throat irritation) persist beyond 30 minutes.

### Ingestion

Do NOT induce vomiting. Rinse mouth thoroughly with water. Give the person 1-2 glasses of water to drink if conscious and able to swallow. Do not give anything by mouth to an unconscious person. Seek immediate medical attention. Bring this MSDS and product label to the treating physician.

## 02 Spill / abnormal reaction

- Restrict access and stop exposure.
- Wear task-appropriate PPE before approaching the spill.
- Prevent uncontrolled spread to drains or incompatible materials.
- Use the current SDS Section 6 for containment and cleanup.
- Escalate large spills, fumes, fire, strong or unexpected chemical odour, unexpected heat or incompatible mixing immediately.



# Storage, training and deviation control

Safe use depends on correct storage, competent operators and disciplined stop-work behaviour.

## 01 Storage controls

7.1 Precautions for Safe Handling General Read label and MSDS before use. Use only as directed. Avoid contact with eyes and prolonged skin contact. Ventilation Use in well-ventilated areas. Avoid generating aerosol mist in enclosed spaces. Hygiene Wash hands thoroughly with soap and water after handling. Do not eat, drink, or smoke during use. PPE Gloves and eye protection recommended for concentrate handling Incompatibilities Do not mix with bleach, strong acids, strong alkalis, or oxidising agents unless explicitly specified on the label. Dilution 1:5 to 1:20 depending on soil level Spills

## 02 Operator competency

- Identify the correct product, label and current SDS.
- Explain the approved dose/dilution and application sequence.
- Select and use task-appropriate PPE.
- Recognise incompatible chemicals/materials and stop-work conditions.
- Perform rinse/finish and verification steps correctly.
- Report and document spills, exposures, damage and deviations.

## 03 Deviation rule

### Do not improvise

If the task, surface, chemistry, dose, contact time, PPE or incident condition is outside the current controlled instructions, stop and obtain technical/supervisor approval before continuing.

# Resources, approval and revision

Use the website as the current document layer and retain local approval and revision records for controlled use.

## 01 Live resources



### Current SDS

Safety data



### Document centre

SDS / TDS / guides



### Shop

Browse / procure

## 02 Approval record

PREPARED BY

Alle's ClinX Technical Documentation

TECHNICAL REVIEWER

\_\_\_\_\_

EHS / OPERATIONS REVIEWER

\_\_\_\_\_

EFFECTIVE DATE

\_\_\_\_\_

REVISION

1.0

NEXT REVIEW

\_\_\_\_\_

## 03 Release condition

Use this SOP with the current formulation, product label, SDS/TDS, applicable site controls and product-specific technical instructions.