

Passivation Metal Descaler - Mild Acid

Mild Acid Chemistry with Non-Abrasive Formula, 1:4 Dilution + Passivation Action Metal Surface Descaling for stainless steel, chrome & aluminium in institutional kitchens

01 Document control

DOCUMENT ID

ACX-SOP-ACX1232VAR

STATUS

Professional facility use

MARKET

India

SOURCE BASIS

Current Alle's ClinX product catalogue + current public SDS

02 Control requirement

Use with the current label, SDS, technical instructions and site-specific controls.

03 Purpose

Define a repeatable, supervised and documented method for professional use of Passivation Metal Descaler - Mild Acid, including preparation, PPE, dose/dilution, application, verification, incident response and storage.

Scope, roles and stop-work authority

Defines who may use the product, what each role controls, and when work must stop.

01 Scope

Mild Acid Chemistry with Non-Abrasive Formula, 1:4 Dilution + Passivation Action Metal Surface Descaling for stainless steel, chrome & aluminium in institutional kitchens

02 Roles

Supervisor / facility lead

Operator

Approve task fit, confirm current controlled Follow dose/dilution and sequence exactly; use documents, ensure PPE/access controls and PPE; stop work when conditions fall outside the review deviations. SOP.

EHS / technical reviewer

Procurement / stores

Resolve uncertain compatibility, exposure, Maintain labelled stock, correct segregation, incident or formulation questions before work current revision documents and traceable resumes. product identity.

03 Stop-work authority

- Unexpected reaction, heat, fumes, odour or visible surface attack.
- Damaged or unlabelled container, uncertain product identity or uncertain compatibility.
- Splash/exposure event or uncontrolled spill.

Hazard controls before product handling

Use the current SDS classification and task risk assessment; product appearance or fragrance is not a safety control.

01 Current SDS hazard profile



WARNING GHS07

H315 - Causes skin irritation. H319 - Causes serious eye irritation (concentrate).

02 PPE selection



Protective gloves



Eye protection

03 Primary failure modes

01 Skin / eye irritation

Minimise concentrate contact and splashing; use task-appropriate PPE.

02 Mist / spray

Avoid unnecessary aerosol generation; ventilate enclosed work areas.

03 Wrong dilution / dose

Measure product; do not free-pour where a defined dilution or dose is specified.

04 Incompatible chemistry

Never mix cleaning chemicals unless current controlled documentation explicitly permits it.

Pre-use checklist

No application begins until product identity, compatibility, area controls, PPE and cleanup resources are confirmed.

01

Read current SDS

Confirm current label/SDS and site procedure before use.

02

Confirm application

Use only for the intended task, surface, equipment or hygiene purpose.

03

Prepare the area

Control access, remove incompatible products and arrange ventilation where needed.

04

Prepare PPE

Use the PPE stated in the SDS/product literature for concentrate handling and task risk.

05

Prepare rinse / cleanup

Have water, wipes or approved cleanup materials ready before starting.

01

Product setup

DOSE / DILUTION

250 ml per litre of water (1:4)

APPLICATION

Soft cloth or spray - direction of metal grain

RINSE / FINISH

Mandatory on food-contact surfaces - thorough water rinse

Step-by-step operating procedure

250 ml per litre of water (1:4) | Soft cloth or spray - direction of metal grain

Prepare

01

Read the current label/SDS, confirm compatibility, isolate the task area and prepare PPE.

Dose / dilute

02

250 ml per litre of water (1:4)

Apply as directed

03

Dilution 250 ml of concentrate per litre of water (1:4 ratio).

Apply as directed

04

Apply with a soft cloth or spray bottle - do not use abrasive pads or steel wool.

Rinse / finish

05

Mandatory on food-contact surfaces - thorough water rinse

Verify

06

Confirm the required result, correct finish and safe condition before closing the task.

Quality verification and task release

Application alone is not completion; verify the result and confirm the area is safe to return to service.

01 Completion criteria

- Required soil / contamination / hygiene task has been addressed to the facility standard.
- No visible chemical residue remains where the process requires rinsing or wipe-off.
- No material damage, discolouration, etching, swelling or finish change is visible.
- Area, equipment or item is safe to return to service.
- Container is closed, labelled and returned to the correct storage location.
- Any deviation, repeat cycle, spill, exposure or damage is recorded and escalated.

02 Process data to record

Date / location

Product / batch

Where and when the task occurred. Product identity and batch/lot where available.

Dose / dilution

Operator / supervisor

Actual measured amount or working dilution. Who performed and who released the task.

Deviation / incident

Any repeat, damage, spill, exposure or unusual result.

Surface, material and equipment compatibility

Identify the material before application. Compatibility failures are preventable when limits are checked first.

01 Compatibility matrix

Compatible after check

- Stainless steel
- chrome
- treated aluminium
- architectural metalwork

Verify before use

- Copper
- brass
- reactive metals - test before use

02 Use-case boundaries

01 Provides controlled acidic action for compatible mineral-scale and deposit-removal tasks.

02 Supports cleaning without abrasive mechanical action on compatible surfaces.

03 Supports measured dosing across the stated dilution or application range.

04 Use only on compatible materials and within the current product, site and food-safety controls.

Exposure, spill and abnormal reaction

Stop the task, protect people first, then contain and escalate according to the current SDS and site emergency procedure.

01 First aid

Eyes

ACT IMMEDIATELY. Flush eyes with clean water for a minimum of 15 minutes, holding eyelids open and rolling eyes to ensure full irrigation. Remove contact lenses if present and easy to do - continue rinsing. Seek immediate medical/ophthalmological attention even if no symptoms are present.

Skin

Immediately remove contaminated clothing including shoes. Flush affected skin with large amounts of water for at least 15 minutes. Do not scrub. Apply soap if available after initial rinsing. If irritation, redness, or pain persists, seek medical attention. Wash clothing before reuse.

Inhalation

Remove affected person to fresh air immediately. If breathing is difficult, administer oxygen. If breathing has stopped, apply artificial respiration. Keep person warm and at rest. Seek medical attention if symptoms (coughing, throat irritation) persist beyond 30 minutes.

Ingestion

Do NOT induce vomiting. Rinse mouth thoroughly with water. Give the person 1-2 glasses of water to drink if conscious and able to swallow. Do not give anything by mouth to an unconscious person. Seek immediate medical attention. Bring this MSDS and product label to the treating physician.

02 Spill / abnormal reaction

- Restrict access and stop exposure.
- Wear task-appropriate PPE before approaching the spill.
- Prevent uncontrolled spread to drains or incompatible materials.
- Use the current SDS Section 6 for containment and cleanup.
- Escalate large spills, fumes, fire, strong or unexpected chemical odour, unexpected heat or incompatible mixing immediately.

Storage, training and deviation control

Safe use depends on correct storage, competent operators and disciplined stop-work behaviour.

01 Storage controls

7.1 Precautions for Safe Handling General Read label and MSDS before use. Use only as directed. Avoid contact with eyes and prolonged skin contact. Ventilation Use in well-ventilated areas. Avoid generating aerosol mist in enclosed spaces. Hygiene Wash hands thoroughly with soap and water after handling. Do not eat, drink, or smoke during use. PPE Gloves recommended Incompatibilities Do not mix with bleach, strong acids, strong alkalis, or oxidising agents unless explicitly specified on the label. Dilution 250 ml per litre of water (1:4) Spills Clean up spills immediately. Wet surfaces may be

02 Operator competency

- Identify the correct product, label and current SDS.
- Explain the approved dose/dilution and application sequence.
- Select and use task-appropriate PPE.
- Recognise incompatible chemicals/materials and stop-work conditions.
- Perform rinse/finish and verification steps correctly.
- Report and document spills, exposures, damage and deviations.

03 Deviation rule

Do not improvise

If the task, surface, chemistry, dose, contact time, PPE or incident condition is outside the current controlled instructions, stop and obtain technical/supervisor approval before continuing.

Resources, approval and revision

Use the website as the current document layer and retain local approval and revision records for controlled use.

01 Live resources



Current SDS

Safety data



Document centre

SDS / TDS / guides



Shop

Browse / procure

02 Approval record

PREPARED BY

Alle's ClinX Technical Documentation

TECHNICAL REVIEWER

EHS / OPERATIONS REVIEWER

EFFECTIVE DATE

REVISION

1.0

NEXT REVIEW

03 Release condition

Use this SOP with the current formulation, product label, SDS/TDS, applicable site controls and product-specific technical instructions.