

Alle's ClinX

STANDARD OPERATING PROCEDURE

Passivation Metal Descaler - Mild Acid

SKU	ACX-1232-VAR
Brand	Alle's ClinX

1. Purpose

Defines document-control and safety checkpoints for authorized use of this product without replacing the product label, SDS, risk assessment, or site-specific work instruction.

2. Scope

Applies to trained staff who are authorized by the site to handle this product within an approved task or process.

3. Responsibilities

Role	Responsibility
Site / QA / EHS	Maintain the approved label, SDS, risk assessment, and controlled work instruction.
Supervisor	Confirm staff authorization, training, and document availability before work begins.
Operator	Follow the current controlled documents exactly and stop work if any information is unclear or inconsistent.

4. Pre-task verification

- Confirm the container label matches the product name and SKU shown above.
- Ensure the current SDS and site-approved work instruction are available.
- Use the PPE and engineering controls specified by the current SDS/site risk assessment.
- Keep the product in its correctly labelled container and away from incompatible materials.

5. Execution control

Carry out the task only under the current approved work instruction and product label. No chemical-use parameters are reproduced in this publishing-safe SOP.

6. Completion & records

Close and secure the product container, return it to the approved storage location, and complete the site's required task/QA record. Report damaged packaging, exposure, spills, label discrepancies, or document conflicts through the site's incident/deviation process.

STOP WORK if the product identity, SDS, PPE requirements, approved procedure, or container condition is uncertain.