## Internal Check & Test Procedure BoQ Plan Actual Region: Clanzin Address: X 632CJR 00257/Grya Cironjang, X 632CJR 00079/Parm Ciferry Locans X 132 CJR 00156 14d /Protunnes samolo, X 132 COR 00363, 395,317, Perumpoternis BoQ Actual (Redline) +/-Unit BoQ Plan (WO) No. Pole 9m, 5inch Unit Pole 7m, 4inch Unit Pole 7m, 3inch (HC) Unit FDT Unit FAT 5 Unit Cable 24 core M1 Cable 36 core M1 Cable 48 Core M1 4 Joint Closure 9 Unit 10 | Splitter 1:16 Unit 11 Sling wire M1 Ahile Sambingo 8 8 Comments: Signatures: Responsible Subcontractor Responsible Mandor Name: Name: About Marry Signature