Internal Check & Test Procedure BoQ Plan Actual Region: Clonjur Link From: Address: XL32 CJR 00112 (Open Area Bataken Caringin) / XLZCJR 00403 (Open An Babalon (aringin) / XL32CJR 60241 (Masjid Graho Samole) BoQ Actual (Redline) No. Item BoQ Plan (WO) 1 Pole 9m, 5inch Unit Pole 7m, 4inch Unit Pole 7m, 3inch (HC) Unit 4 FDT Unit FAT Unit Cable 24 core Cable 36 core M1 Cable 48 Core M1 Joint Closure Unit Splitter 1:16 Unit 11 Sling wire M1 12. Sababungan di FOT 3 Titile, sambungan Closure Quising 1 titile 10tal sambungan 5 Titik Signatures: Responsible Subcontractor Responsible Mandor Name: Abrar Nasrul