Internal Check & Test Procedure BoQ Plan Actua Region: Link From Address Address					
	VPS	-Uso Rehors	OTI ARO		eccinantes como mantes consumente. Addresse;
No.	Item	BoQ Plan (WO)	BoQ Actual (Redline)	+1-	Unit
1	Pole 9m, 5inch				Unit
2	Pole 7m, 4inch				Unit
3	Pole 7m, 3inch (HC)				Unit
4	FDT				Unit
5	FAT				Unit
6	Cable 24 core				M1
7	Cable 36 core			,	M1
8	Cable 48 Core				M1
9	Joint Closure				Unit
10	Splitter 1:16				Unit
11	Sling wire				M1
12	OTOR		46		Core
	ments:				
	tures: Druv ture:			Responsible Mand	

	Region:	- 931- Sidoyo		Check & Te	BoQ Plan Actual Link From: Address:
		- 331- 010040	JU ZIIEW		Address:
No.	ltem	BoQ Plan (WO)	BoQ Actual (Redline)	+/-	Unit
1	Pole 9m, 5inch				Unit
2	Pole 7m, 4inch				Unit
3	Pole 7m, 3inch (HC)				Unit
4	FDT				Unit
5	FAT				Unit
6	Cable 24 core				М1
7	Cable 36 core				M1
8	Cable 48 Core				M1
9	Joint Closure				Unit
10	Splitter 1:16				Unit
11	Sling wire				M1
12	OTOR		24		Core
	nents:				
Signat Respo U. ID: Signat	nsible Subcontractor Name:			Responsible Mando	or Name:
			2		

	Region:DS E	363- Sidod		Check & Te	BoQ Plan Actual Link From: Address:
No.	Item	BoQ Plan (WO)	BoQ Actual (Redline)	+/-	Unit
1	Pole 9m, 5inch		i i		Unit
2	Pole 7m, 4inch				Unit
3	Pole 7m, 3inch (HC)				Unit
4	FDT				Unit
5	FAT				Unit
6	Cable 24 core				M1
7	Cable 36 core				M1
8	Cable 48 Core				M1
9	Joint Closure				Unit
0	Splitter 1:16				Unit
1	Sling wire				M1
2	OTOR		97		Core
ınatı	ures: usible Subcontractor Name:			Responsible Mand	for Name:
					Mar

Internal Check & Test Procedure **BoQ Plan Actual** Peglon: DSB 535 - Sidolopo Wetan Link From: Address: No. Item BoQ Plan (WO) **BoQ Actual (Redline)** 41-Unit Pole 9m, 5inch 1 Unit 2 Pole 7m, 4inch Unit 3 Pole 7m, 3inch (HC) Unit Unit 4 FDT Unit 5 FAT 6 Cable 24 core M1 M1 7 Cable 36 core 8 Cable 48 Core M1 Unit 9 Joint Closure Unit 10 Splitter 1:16 M1 11 Sling wire 44 Care OTDR Comments: Signatures: Responsible Subcontractor Name: Responsible Mandor Name: Signature

Internal Check & Test Procedure

BoQ Plan Actual Link From: Address:

Region: DSB 154 4 - SimPang Dukuh 2

No.	Item	BoQ Plan (WO)	BoQ Actual (Redline)	+1-	Unit
1	Pole 9m, 5inch				Unit
2	Pole 7m, 4inch	-		mental y dispersion and	" Unit
3	Pole 7m, 3inch (HC)			Control of the Contro	Unit
4	FDT				Unit
5	FAT				Unit
6	Cable 24 core				M1
7	Cable 36 core	1			M1
8	Cable 48 Core				M1
9	Joint Closure				Unit
10	Splitter 1:16				Unit
11	Sling wire				M1
12	OTOR		28	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	core

7	Cable 36 core			A Description of Same Same Same	M1
8	Cable 48 Core			7	M1
9	Joint Closure				Unit
10	Splitter 1:16				Unit
11	Sling wire				М1
12	OTDR		28	91 Vo. 1870 P.	core
	nsible Subcontractor Name:			Responsible Mando	
D ID: Signati	ure:	•		Nuke 1	My Many D

	Region:				est Procedure BoQ Plan Actual Link From:
	DSB	489 - POS	of kuras Mady	CA	Address:
No.	Item	BoQ Plan (WO)	BoQ Actual (Redline)	+/-	Unit
1	Pole 9m, 5inch				Unit
2	Pole 7m, 4inch	*			Unit
3	Pole 7m, 3inch (HC)	9	7		Unit
4	FDT				Unit
5	FAT				Unit
6	Cable 24 core			11	М1
7	Cable 36 core				M1
8	Cable 48 Core				M1
9	Joint Closure				Unit
10	Splitter 1:16				Unit
11	Sling wire				M1
12	OTOR		કર્જ		Core
25 (*)	ments:				
Respo	tures: onsible Subcontractor Name: Down			Responsible Mande	or Name:
D: Signa	tura:			Signature	hat
ļ.,	en de la companya de La companya de la co				

	Basican		Interna	Check & Te	BoQ Plan Actual
	Region:	D9B 049 - 3	semoloworu		Address:
No.	Item	BoQ Plan (WO)	BoQ Actual (Redline)	+/-	Unit
1	Pole 9m, 5inch				Unit
2	Pole 7m, 4inch				Unit
3	Pole 7m, 3inch (HC)				Unit
4	FDT				Unit
5	FAT				Unit
6	Cable 24 core				M1
7	Cable 36 core				M1
8	Cable 48 Core				M1
9	Joint Closure				Unit
10	Splitter 1:16				Unit
11	Sling wire				M1
12	CTOR		32		Core
	ments:				
Respo	ntures: onsible Subcontractor Nar	ne:		Responsible Man	
D: Signa	Dever'			ID: Signature	(rwant)
_				10	Mount