## DATA PUNCHLIST NEED RECTIFICATION AREA: SOLO/KLATEN

CITY	NO	SITE ID	SITE NAME	ITEM PUNCHLIST	Column1		REMARKS
SOLO	1	SF07-05-068	SF PUCANGAN RW 08	P002 EXT Pucangan 09 acc ganti dead end	Columnia		KEIVIANNS
		0.0.00		P006 EXT Pucangan 09 acc ganti dead end			
	2	SF07-05-067	SF PUCANGAN RW 09	KTS S02 P30 EXT rapikan posisi JC		IDR	450.000,00
				P001 acc ganti dead end			
				P003 acc ganti dead end			
				P004 acc ganti dead end			
				P009 acc ganti dead end			
				P034 acc ganti dead end			
				P008 repair cor			
				P008 spare banding			
				P014 rapikan slack kabel dan posisi acc			
				P025 repair cor			
				P015 repair cor			
	2	CL DOZ OF 025	IVADANICACENA DIAVOO	P022 repair acc (suspensi lepas)		100	1 000 000 00
	3	CLR07-05-025	KARANGASEM RW 09	All label pole		IDR	1.000.000,00
				All acc			
				All label kabel			
				P 005 FAT A3 geser posisi FAT			
				P FAT B 5 POLE DIKASIH PIPA (dekat dengan listrik)			
				P 036 ext krngsm 4 ganti deadend			
	4	SF07-05-025	SF KARANGASEM RW 09	All label kabel		IDR	350.000,00
		0.07 03 023	27 IU IIU III O IOEIVI IVV 03	P 009 ext SF krngasem 4 acc lepas		.5.1	220.000,00
				P 004 ext SF krngasem 4 acc terlalu tinggi			
				P 001 ext SF kabel kendor			
	5	SF07-02-131	SF PAJANG RW 03	Pulling Cabel 48c 300san meter		IDR	300.000,00
				Instal pole 2 Batang			,
				Dismentle Cable 48 -/+ 800m			
				Joint fo 6core . Fdt 3core JC ext mf 3 core			
KLATEN	1	CLR20-99-042	BUNTALAN RW 11	P001 miring		IDR	350.000,00
				P004 miring			
				P007 miring			
				P015 miring			
				P001 repaint pole	20000	IDR	350.000,00
				P002 repaint pole	20000		
				P003 repaint pole	20000		
				P004 repaint pole	20000		
				P006 repaint pole	20000		
				P007 repaint pole	20000		
				P009 repaint pole	20000		
				P010 repaint pole	20000		
				P011 repaint pole	20000		
				P012 repaint pole P013 repaint pole	20000 20000		
				P014 repaint pole	20000		
				P015 repaint pole	20000		
				P003 cor ulang	20000	IDR	450.000,00
				P005 acc lepas			
				P006 banding kabel			
				P007 banding kabel			
				P010 banding kabel			
				P014 banding kabel			
				P008 acc ganti dead end			
				P013 acc ganti dead end			
				P009-P010 add sling			
				P011 repair cor			
				P013 repair cor			
				P015 unspec			
				P002 cor aci (add)			
				P012 label kabel (add)			
		CE20 00 017	CE DUINTAL AND DOLLAR	P014 Slack kabel (add)			
	2	SF20-99-042	SF BUNTALAN RW 11	Perapihan slack kabel JC		IDC	600,000,00
	3	CLR20-99-002	KARANGANOM RW 06	P001 label pigtail & ps 1:8 belum dipasang		IDR	600.000,00
				P008 perapihan slack kabel FAT C01 P009 banding cabel			
				P010 perapihan slack kabel fat C02			
				P013 perapihan slack kabel fat C03			
				P015, P016 pasang conduit kabel yang kena genteng			
				P016 banding cabel			
				30			

POLS peraphan slack kabel fat COS POLO ACC gant idea dend POLO peraphan slack kabel fat COS HC POLO peraphan slack kabel fat COS POLO peraphan slack fat Fat Polo peraphan slack fat Polo				P017 perapian slack kabel fat C04				
P020 peraphlan slack kabel fat C06								
P023 ganti tiang reguler , banding cabel   P025 perapihan slack kabel fat CO7   P026 ACC ganti dead end   P028 perapihan slack kabel fat CO8   P028 perapihan slack FAT   P001 tabel pole belum   P028 perapihan slack FAT   P002 regular pole   P028 perapihan slack FAT   P003 tabel pole terbalik   P003 repaihan slack FAT   P003 repaihan slack FAT   P003 perapihan slack FAT   P003 perapihan slack FAT   P003 perapihan slack FAT   P003 perapihan slack FAT   P003 tabel pole terbalik   P003 terpaihing   P003 terpaihing   P003 perapihan slack FAT   P004 pole mining   P005 terpaihing   P005 terpaihing   P005 terpaihing   P005 terpaihing   P005 terpaihing   P005 tabel pole terbalik   P005 tabel pole terbalik   P005 tabel pole terbalik   P006 terpaihing   P009 terpaihing   P009 terpaihing   P009 terbalik   P009 terpaihing   P009 terbalik   P006 terbalik   P006 terbalik   P006 terbalik   P006 terpaihing   P009 terbalik   P006 terbalik   P009 terpaihing   P009 terbalik   P009 terpaihing								
P025 perapihan slack kabel fat C07   P026 ACC ganti dead end   P028 perapihan slack kabel fat C08   P028 perapihan slack fat P028 perapihan slack fat P028 pool pole terbalik   P028 pool pole pole fat Fat P028 pole perapihan slack fat P028 pole pole pole pole pole pole pole pole								
P026 ACC ganti dead end   P028 peraphina stack kabel fat C08   P026 peraphina stack kabel fat C08   P026 peraphina stack kabel fat C08   P026 peraphina stack fat P026 peraphina stack fat P026 peraphina stack fat P026 peraphina fack fat P026 peraphina fack fat P026 peraphina fack fat P026 peraphina fack fat P020 peraphina fack p020 peraphina fack fat F020 peraphina fack fat P020 peraphina fack fat F020 peraphina fack fat P020 peraphina fack fat F020 peraphi								
P028 perapihan slack kabel fat C08				·				
HC P003 label pole belum   HC P004 sling belum di pasang   HC P001 reguler ganti hc   HC P001 reguler ganti hc   HC P002 regular ganti hc   HC P002 regular ganti HC   P17, P18 longspan   HC P001 regular pole reguler + hc   HC P002 regilar pole   IDR 20,000,00   IDR 450,000,00   P003 repaint pole   IDR 20,000,00   IDR 450,000,00   P005 repaint pole   IDR 20,000,00   P007 repaint pole   IDR 20,000,00   P007 repaint pole   IDR 20,000,00   P007 repaint pole   IDR 20,000,00   P011 repaint pole   IDR 20,000,00   P012 repaint pole   IDR 20,000,00   P015 repaint pole   IDR 20,000,00   P019 repaint pole				Ü				
HC P004 sling belum di pasang   HC P001 reguler ganti hc   HC P002 regular ganti hC   HC P002 regular ganti HC   P17, P18 longspan   All repain pole reguler + hc   P002 regular pole   IDR   20.000,00   IDR   450.000,00   P003 repaint pole   IDR   20.000,00   IDR   450.000,00   P003 repaint pole   IDR   20.000,00   P004 repaint pole   IDR   20.000,00   P004 repaint pole   IDR   20.000,00   P005 repaint pole								
HC P001 reguler ganti hc   HC P002 regular ganti HC   HC P002 regular ganti HC   P17, P18 longspan   All repain pole reguler + hc   P002 repaint pole   IDR   20.000,00   IDR   450.000,00   P003 repaint pole   IDR   20.000,00   IDR   20.000,00   P005 repaint pole   IDR   20.000,00   P006 repaint pole   IDR   20.000,00   P007 repaint pole   IDR   20.000,00   P008 repaint pole   IDR   20.000,00   P010 repaint pole   IDR   20.000,00   P010 repaint pole   IDR   20.000,00   P011 repaint pole   IDR   20.000,00   P011 repaint pole   IDR   20.000,00   P012 repaint pole   IDR   20.000,00   P013 repaint pole   IDR   20.000,00   P015 repaint pole   IDR   20.000,00   P015 repaint pole   IDR   20.000,00   P015 repaint pole   IDR   20.000,00   P016 repaint pole   IDR   20.000,00   P017 repaint pole   IDR   20.000,00   P018 repaint pole   IDR   20.000,00   P019 repaint				•				
HC P002 regular ganti HC   P17, P18 longspan   All repain pole reguler + hc								
P17, P18 longspan								
All repain pole reguler + hc  4								
A   CLR20-01-221   KETANDAN RW 06   P002 repaint pole   IDR   20.000,00   IDR   450.000,00   P003 repaint pole   IDR   20.000,00   P006 repaint pole   IDR   20.000,00   P007 repaint pole   IDR   20.000,00   P007 repaint pole   IDR   20.000,00   P008 repaint pole   IDR   20.000,00   P008 repaint pole   IDR   20.000,00   P011 repaint pole   IDR   20.000,00   P012 repaint pole   IDR   20.000,00   P014 repaint pole   IDR   20.000,00   P014 repaint pole   IDR   20.000,00   P015 repaint pole   IDR   20.000,00   P016 repaint pole   IDR   20.000,00   P016 repaint pole   IDR   20.000,00   P017 repaint pole   IDR   20.000,00   P018 repaint pole   IDR   20.000,00   P018 repaint pole   IDR   20.000,00   P019 repaint pole   IDR   20.000,00   P019 repaint pole   IDR   20.000,00   P020 repaint								
P003 repaint pole   IDR				1 1 0				
P006 repaint pole   IDR   20.000,00	4	CLR20-01-221	KETANDAN RW 06	·			IDR	450.000,00
P007 repaint pole   IDR   20.000,00				·		•		
P008 repaint pole   IDR   20.000,00     P010 repaint pole   IDR   20.000,00     P011 repaint pole   IDR   20.000,00     P012 repaint pole   IDR   20.000,00     P014 repaint pole   IDR   20.000,00     P015 repaint pole   IDR   20.000,00     P016 repaint pole   IDR   20.000,00     P017 repaint pole   IDR   20.000,00     P018 repaint pole   IDR   20.000,00     P019 repaint pole   IDR   20.000,00     P020 repaint pole   IDR   20.000,00     P021 repaint pole   IDR   20.000,00     P022 repaint pole   IDR   20.000,00     P023 perapihan slack FAT   IDR   300.000,00     P024 label pole terbalik   P025 label pole terbalik   P025 label pole terbalik   P026 banding kabel   P026 cor aci   IDR   335.000,00     P011-P012 kabel kendor   P020 pole miring   P020 pole					IDR	•		
P010 repaint pole   IDR   20.000,00     P011 repaint pole   IDR   20.000,00     P012 repaint pole   IDR   20.000,00     P014 repaint pole   IDR   20.000,00     P015 repaint pole   IDR   20.000,00     P015 repaint pole   IDR   20.000,00     P016 repaint pole   IDR   20.000,00     P017 repaint pole   IDR   20.000,00     P018 repaint pole   IDR   20.000,00     P019 repaint pole   IDR   20.000,00     P019 repaint pole   IDR   20.000,00     P020 repaint pole   IDR   20.000,00     P030 perapihan slack FAT   IDR   300.000,00     P030 perapihan slack FAT   IDR   20.000,00     P030 perapihan slack FAT   IDR   20					IDR	•		
P011 repaint pole				P008 repaint pole	IDR	20.000,00		
P012 repaint pole   IDR				P010 repaint pole	IDR	20.000,00		
P014 repaint pole				P011 repaint pole	IDR	20.000,00		
P015 repaint pole				P012 repaint pole	IDR	20.000,00		
P016 repaint pole   IDR   20.000,00				P014 repaint pole	IDR	20.000,00		
P017 repaint pole				P015 repaint pole	IDR	20.000,00		
P018 repaint pole				P016 repaint pole	IDR	20.000,00		
P019 repaint pole				P017 repaint pole	IDR	20.000,00		
P020 repaint pole				P018 repaint pole	IDR	20.000,00		
P003 perapihan slack FAT				P019 repaint pole	IDR	20.000,00		
P007 perapihan slack FAT P011 perapihan slack FAT P004 label pole terbalik P005 label pole terbalik P006 banding kabel P006 cor aci P011-P012 kabel kendor P020 pole miring P001 HC repaint (add)  5 SF20-10-221 SF KETANDAN RW 06 Perapihan slack kabel JC ext Mlese RW 02				P020 repaint pole	IDR	20.000,00		
P011 perapihan slack FAT P004 label pole terbalik P005 label pole terbalik P006 banding kabel P006 cor aci P011-P012 kabel kendor P020 pole miring P001 HC repaint (add)  5 SF20-10-221 SF KETANDAN RW 06 Perapihan slack kabel JC ext Mlese RW 02				P003 perapihan slack FAT			IDR	300.000,00
P004 label pole terbalik P005 label pole terbalik P006 banding kabel P006 cor aci P011-P012 kabel kendor P020 pole miring P001 HC repaint (add)  5 SF20-10-221 SF KETANDAN RW 06 Perapihan slack kabel JC ext Mlese RW 02				P007 perapihan slack FAT				
P004 label pole terbalik P005 label pole terbalik P006 banding kabel P006 cor aci P011-P012 kabel kendor P020 pole miring P001 HC repaint (add)  5 SF20-10-221 SF KETANDAN RW 06 Perapihan slack kabel JC ext Mlese RW 02				P011 perapihan slack FAT				
P006 banding kabel								
P006 banding kabel				P005 label pole terbalik				
P006 cor aci				•				
P011-P012 kabel kendor P020 pole miring P001 HC repaint (add)  5 SF20-10-221 SF KETANDAN RW 06 Perapihan slack kabel JC ext Mlese RW 02				- U			IDR	335.000.00
P020 pole miring P001 HC repaint (add)  5 SF20-10-221 SF KETANDAN RW 06 Perapihan slack kabel JC ext Mlese RW 02								
P001 HC repaint (add)  5 SF20-10-221 SF KETANDAN RW 06 Perapihan slack kabel JC ext Mlese RW 02								
5 SF20-10-221 SF KETANDAN RW 06 Perapihan slack kabel JC ext Mlese RW 02								
	5	SF20-10-221	SE KETANDAN RW 06					
		5. 20 10 221	2				IDR	4.935.000 00

Telah terima dari

PT. Ansında

Using sejumlah Figa Juta Dua Ratus Tujuh Puluh Tujuh
RIBU TUJUH Ratus Lima Duluh Rupiah Untuk pembayaran

Pekeryaan site Pektif solo-klaten

5010,

3,277.750

W. Aryon Yalma



NSPORT C	RDER	No. 01727
lama	: Bp. Wideya Argun Valmano	. Telp :
lo. Identitas	: -	
lamat	-	
ipe Mobil	: Grandmax Pick up	AB 8548 ZZ
ujuan	Solo	
anggal Pakai	: 16 Jan 2024 s/dT	anggal: 23 Oan 2024
arga	Pp. 250.000 × 7 HR	unggur
otal Harga	Pb. 1. 750.000, -	
erbilang	* Satu Juta Tujuh Rotus	Limo Puluh Ribu Rupiah *
eterangan		
		Solo, 16 /01/2024