## **Internal Check & Test Procedure**

**BOQ Plan Actual** 

Region :	DEPOK			
Link From:	SF44-03-021 Subfeede	er Cipayung Jaya F	Rw 02 - MANDOR	
Address :				
Item	BoQ Plan (WO)	BoQ Actual (Redline)	+/-	Unit
	0	0		Unit
Pole 7m,	0	0		Unit
Pole 7m, 3inch	0	0		Unit
Cable 24 Core	0	0		M1
Cable 48	400	400		M1
Slack Hanger	0	0		Unit
Sling Wire	0	0		M1
Label Kabel	20	20		Pcs
Label Pole	0	0		Unit
ments:				
onsible Subcontractor			Responsible Mandor Name: UCUP	
ature:			ID: Signature	
JW			Imp	
	Link From :  Address :  Item  Pole 9m, 5lnch  Pole 7m, 5inch  Cable 24 Core  Cable 48 Core  Slack Hanger  Sling Wire  Label Kabel  Label Pole	Item BoQ Plan (WO)  Pole 9m, 5Inch  Pole 7m, 5inch  O Pole 7m, 3inch  Cable 24 Core  Cable 48 Core  Slack Hanger  O Sling Wire  Label Kabel  Label Pole  O  Label Pole  O	Item	Link From : SF44-03-021 Subfeeder Cipayung Jaya Rw 02 - MANDOR