Project Name

: EMR FTTH PROJECT

Cluster Name

: Telaga Pasir Raya RW 12

Cluster ID ATP Date

No	Defect Item		Target Date
J.	Stack Peragricus ALT POT OF	75	2029
3.	Cat, Ulang HCOG + Praythan Flink Will		46
4-	paraphan runk wire roc + 1511 + 1512 physol		-th
у. 6.	labor par 613 + praginon sum win		
	151 510 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
		SCALE PAPER	

Repaired Date	Sign (customer)
12029.	1 1 1/2
7	21/2
PEB	15

Responsible Vendor

Signature: Date:

Responsible Vendor

Signature: Date:

Chater Name **Guster ID**


: EMR FITH PROJECT

: SF Telaga Pasir Raya RW 12

ATP Date

: 15. 02.2029

No	Defect Item	Target Date
	NO RMCHUPP	



Signatures:

Responsible Customer

Responsible Vendor



BERITA ACARA RECTIFIKASI PUNCH LIST

Kamis tanggal \\ \\ \ \ , bulan 3 , tahun عور , kami yang bertanda tangan di bawah ini

Suhanyo


: YOFC International Indonesia

anakan pengecekan ulang untuk hasil rektifikasi punch list Civil Work seperti dibawah ini dengan hasil ERIMA.

: SF Telaga Pasir Raya RW 12

15-02-2014

٠	Defect Item	Defect Description	ption	Punch Point Type	Result	Date of Clearence
	Label	No HH label		Minor)
0.3		No FDT label		Minor		
		No FAT label		Minor		
配人		No Cable label		Minor		
1		No Pole label		Minor		
		NO PUNC	MAHUST			
)			
13						
-						
36	N. Carlotte and Carlotte					1
	The state of the late of the state of the st		The second second			





Shape 8

Acceptance Test Procedure Checklist for Fiber Distribution Terminal (FDT)



ek From:	Dokasi.	To: FDT 01		
riff	Requirements		Comment	
	Check the position of FDT is installed according to	the Design plan	Opassed Ofail ON/A	
ellerh .	Check the stability of FDT fixed on the concrete for Design plan	undation as per	☑passed ☐fail ☐N/A	
	Check the FDT foundation according to the stands	ord design plan	Mpassed ⊡fail ⊡N/A	
	Ensure the FDT body is not damage		Øpassed ☐fail ☐N/A	
	Ensure the FDT adapters are not damage		☑passed ☐fail ☐N/A	
	Ensure the FDT pigtails not damage		Øpassed □fail □N/A	
ndition	Ensure the Splitters Installed properly		Opassed □fail □N/A	
	Ensure the FDT splitters, adapters & connectors a	re using SC/APC	Upassed □fail □N/A	
	Ensure the FDT door can be open and locked prop	perly	☑passed □fail □N/A	
mection	Ensure the connectors are plugged properly		☑passed ☐fail ☐N/A	
	Ensure no pigtail pinched or bending		☑passed □fail □N/A	
	Ensure cable route are installed neat & properly		≝passed □fail □N/A	
ALI FOR	Check the FDT label and numbering according MF	R numbering plan	☑passed □fail □N/A	
hel FDT	Check the cable label and pigtail label		☑passed □fail □N/A	
01	PTPR12.059			
Vendor		Responsible Custom		
over		Name:	legree F.	
W	٤	ID: 6 Signatu		

BERITA ACARA RECTIFIKASI PUNCH LIST

Pada hari ini, tanggal , bulan , tahun , kami yang bertanda tangan di	i bawah	, kami yang bertanda tangan	, tahun	, bulan	tanggal	Pada hari ini,
---	---------	-----------------------------	---------	---------	---------	----------------

: Cubagy o Nama

: YOFC International Indonesia Perusahaan

: Rohmat F Nama : Eka Mas Republik Perusahaan

Telah melaksanakan pengecekan ulang untuk hasil rektifikasi punch list Civil Work seperti dibawah ini dengan hasil BAIK dan DITERIMA.

Cluster Name : Telaga Pasir Raya RW 12

Cluster ID

ATP Date : 15-02-2024

FDT	No	Defect Item	Defect Description	Punch Point Type	Result	Date of Clearence
3430-0.7	1	Label	No HH label	Minor		
			No FDT label	Minor		
			No FAT label	Minor		
			No Cable label	Minor		
			No Pole label	Minor		
	Contract of the	The second second				
			1			
		+				
	-	-	the second secon			
	-					
						
to toxal			a la companya di santana di santa			
					La come de	

ACCEPTANCE TEST PROCEDURE



EMR GPON Project

PT Eka Mas Republik

Cluster Name: TELAGA PASIR RAYA RW 12

Document Prepared by YOFC and Approved by EMR

YOFC Representation:

EMR Representation: RAHMAT PAULI

Smart Link Better Life.

YOFC International Indonesia 2021



Acceptance Test Procedure

Checklist for Fiber Access Terminal (FAT)



Region: Bekasi	Cluster: Telaga Pasir Raya RW 12
Link From: FDT 02_PTPR12,060	To: FAT B03
Address:	Address:

No.	Item	Requirements	Comment
200		Check the position of FAT is installed according to the Design plan	©passed □fail □N/A
1	Position	Check the stability of FAT and or pedestal fixed on pole/pedestal/wall as per the Design plan	☑passed □fail □N/A
		Check the pedestal foundation according to the standard design plan	⊡passed □fail □N
\dashv		Ensure the Pedestal and or FAT body is not damage	⊠passed □fail □N/A
2 Co		Ensure the FAT adapters are not damage	□∕passed □fail □N/A
	Condition	Ensure the FAT pigtails not damage	☑passed ☐fail ☐N/A
		Ensure the FAT adapters & connectors are using SC/APC	☐passed ☐fail ☐N/A
		Ensure the FAT and or pedestal can be open and locked properly	☑passed □fail □N/A
		Ensure the connectors are plugged properly	☑passed □fail □N/A
3 0	Connection	Ensure no pigtail pinched or bending	<i>□</i> passed □fail □N/A
1	Label FAT	Check the FAT label and numbering according MR numbering plan	☑passed □fail □N/A
4		Check the cable label and pigtail label	⊡passed □fail □N/A

omments:

FDT02 #FAT B03

_	_	-	٠.	••	~~	_	
7	п	а	и		re	3	

sponsible Vendor

me: Subasyo

15 02 -10 M

Responsible Customer

fahrer F.

15-62-2029

Name:

Signature

Date:



Acceptance Test Procedure

Checklist for Fiber Access Terminal (FAT)



Region: Bekasi	Cluster: Telaga Pasir Raya RW 12
Link From: FDT 02_PTPR12.060	To: FAT B01
Address:	Address:

No.	Item	Requirements	Comment	
		Check the position of FAT is installed according to the Design plan	Øpassed □fai □N/A	
1	Position	Check the stability of FAT and or pedestal fixed on pole/pedestal/wall as per the Design plan	C∕passed □fail □N/A	
		Check the pedestal foundation according to the standard design plan	☑passed □fail □N/A	
*		Ensure the Pedestal and or FAT body is not damage	≝passed □fail □N/A	
		Ensure the FAT adapters are not damage	Øpassed □fail □N/A	
2	2	Condition	Ensure the FAT pigtails not damage	⊠passed □fail □N/A
			Ensure the FAT adapters & connectors are using SC/APC	☑passed □fail □N/A
			Ensure the FAT and or pedestal can be open and locked properly	☑passed ☐fail ☐N/A
		Ensure the connectors are plugged properly	☑passed □fail □N/A	
3	Connection	Ensure no pigtail pinched or bending	☑passed □fail □N/A	
4		Check the FAT label and numbering according MR numbering plan	☑passed □fail □N/A	
	Label FAT	Check the cable label and pigtail label	Øpassed □fail □N/A	

omments:

DT02 #FAT B01

u	n	-			0	e	
ş	,,	a	tu	и	C	Ð	•

sponsible Vendor

Subayyo

15.02.70m

Responsible Customer

Name:

Remon F.

ID: Signature

Date: 12074