

1st Class Alignment & Repair Inc.

35 Dolson Avenue Middletown, NY 10940 Phone: 845-342-2886 ~ Fax: 845-684-0180

Email: 1stclassar@gmail.com Website: www.firstclassalignment.com Repair Facility # 7107773

Invoice

Bill To Almonte, Luis 12 Estate Drive Middletown, NY 10940 USA

Mobile (917) 769-5847 Email almonteluis92@gmail.com

Invoice # 204393 Work Order # 8626 Service Advisor Gladys Technician Chris

Plate NY HXP8433

Description Gold 2010 Nissan Versa SL L4 1.8L 1798CC

VIN 3N1BC1CP5AL373248

Odometer 105,112

Invoice Date 8/12/2021 5:40 PM

Concern

Service Request / Concern? = cel back on B1 S1 P2A00

Specific Symptoms = cel back on

Drop off

Need car done by or back by: = when done

See Inspection Results - Sent to Customer by Text or Email

Technician: Chris / Service Advisor: Gladys

Sub \$0.00

-- Technician Notes from AutoVitals SmartFlow --

It?s late returns for oxygen sensor may have a bad PCM it?s late returns for timing codes may have a stretched beltlt?s late returns for oxygen sensor may have a bad PCM it?s late returns for timing codes may have a stretched belt

Inspection

Photo Health Care Check

Exterior Photos

Labor

Technician: Chris / Service Advisor: Gladys

Sub \$0.00

Digital Inspection Result(s)

Inspection results from SmartFlow Digital Vehicle Inspections

-- Added by SmartFlow on 8/12/2021 --

Photo Inspection, rev. 1

https://motorist.autovitals.com/l/EgkZLa

Technician: Chris / Service Advisor: Gladys

\$0.00 S

\$0.00 Sub

Service

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 6/30/2021 --

Technician: Chris / Service Advisor: Gladys

Air Filter

\$35.82 S \$20.03 S

\$55.85 Sub

-- Inspection Results from AutoVitals SmartFlow --

For 'Air Filter' the following conditions have been found: Dirty.

* Recommend replacing engine air filter as build up is present.

Supporting Images and Videos:

* Image https://motorist.autovitals.com/l/DqMuTU Recommend replacing engine air filter as build up is present.

For more info, check inspection results https://motorist.autovitals.com/l/DgMuSe.

Air Fuel Ratio Sensor B1 (if code returns for oxygen sensor need to test PCM)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor \$99.50 S Technician: Chris / Service Advisor: Gladys Air Fuel Ratio Sensor (Dealer Part) \$318.58 S Sub \$418.08

Camshaft Position Sensor (Timing could be strectcehed if code returns this is step 1)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

\$71.64 S Technician: Chris / Service Advisor: Gladys

Cam Position Sensor \$85.74 S

\$157.38

Sub

T. (D.)		
Total Parts		\$424.35
Total Labor		\$206.96
Total Before Taxes & Miscellaneous Charges		\$631.31
(S) NY State Sales Tax	8.125 %	\$51.29
Grand Total		\$682.60

WARRANTY: TechNet 2 years/24,000 miles part and labor includes nationwide and roadside protection. 866–588–0728 for all claims 25 miles away from Shop. (Excluding Dealership Parts=1 Year Part Only)

I hereby authorize 1ST Class Alignment and Repair employee's permission to operate my vehicle at their discretion for the purpose of diagnosis. I understand that there is a minimum \$40 diagnostic charge and \$50 daily storage for all vehicles left on premises unless otherwise expressed in writing. We are not responsible for damages or articles left in car due to theft, fire or any other causes beyond our control.

This signature authorizes 1ST Class to charge agreed upon amount due and implies all work is completed.

Thank you for your business!

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

ALMONTE/JORGE paid \$682.60 by Debit

08-12-21 17:40:44 Card #: 407941XXXXXX5239 CHIP READ Inserted Type: Purchase Total: USD\$682.60

Terminal ID: XXXXXXXXXXXXXXX Transaction: 000000004046 Approval: 061933

AID: A0000000980840 AC: 629D6504A2CFCC1E ATC: 004B

TVR: 8080048000 TSI: 6800 Resp CD: Z3

Approved - Thank You / Retain this copy for statement verification

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

Invoice Signature. Signed on 8/12/2021 5:40 PM

Customer Signature:

Authorization(s)

1013e Almant

8/12/2021 1:52 PM \$682.60 Photo Health Care Check

Service Request / Concern? = cel back on B1 S1 P2A00

Air Filter

Air Fuel Ratio Sensor B1

Camshaft Position Sensor (Timing could be strectcehed if code returns this is step 1)