

A CO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجية

تلفون: ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس: ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب: ٢٣٥٥ الجهرام, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 55713

Customer	Aloof Hospital	Equipment	Endoscopy Washer
		Model No.	SERIE 3
		Serial No.	25186
Authorized Person		Manufacturer	Soluscope.
Customer Complaint		Location	Endoscopy
Error: 12		Contract / Order No.	

Services / Check Carried out

- | | |
|--|--|
| ☐ Inspection / Cleaning | ☐ Optics Checks |
| ☐ Calibration / Performance | ☐ Pneumatic Checks |
| ☐ Interface / Communication | ☐ Hydraulic Checks |
| ☐ Safety Checks | ☐ Operational Error |
| ☐ Electrical / Electronics | ☐ Mechanical Checks |
| ☐ Accessories Check | ☐ |

- | | |
|---|---------------------------------|
| ☐ Installation | ☐ Warranty |
| ☒ Repair | ☐ On Charge |
| ☐ Maintenance | ☐ Contract |
| ☐ Upgrade | ☐ |

Time Spent

Remarks

We inspect the unit and found that the Solution injection pump faulty. We replaced the Solution P pump with new one. We replaced all connectors for bottles. & also replaced the Inlet Solution NRV and Pump injection side NRV.

Performed cycle 6 and found that unit is working. Checked and confirmed that the unit is working properly.

No.	Spare Parts Used	Part No.	Qty.
1.	Solution P Pump	SoLo069	1
2.	NRV w/Black		3
3.	NRV w/Red		2
4.	NRV Red		2
5.	Bottle connectors		3

Service Engineer

Authorized Person

Customer / User

Nidam
ATCO Technology Co.

Signature

Signature

Signature

Date

Date

Date

28/07/2024

د. غانم سليمان خليفه الهاشم
طبيب استشاري باطنة مختار حضني
2202020375