

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



log no - 1773

شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهرء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 56775

Customer	Alst Hospital Jahra		
Equipment	X-Ray Machine		
Model No.			
Serial No.			
Authorized Person	Manufacturer Primax		
Customer Complaint	Location X-Ray Department		
Collimator Y axis not moving			
Contract / Order No.			
Services / Check Carried out ☐ Inspection / Cleaning ☐ Calibration / Performance ☐ Interface / Communication ☐ Safety Checks ☐ Electrical / Electronics ☐ Accessories Check ☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐ ☐ Installation ☒ Repair ☐ Maintenance ☐ Upgrade ☐ Warranty ☒ On Charge ☐ Contract ☐			
Time Spent			
Remarks Service call attended. Checked the unit and found the collimator Y-axis shutter motor is stucked condition. Suspecting the motor worn condition. Done some adjustments and working properly after several restarts. In future this happens need replacement of Collimator module.			
No.	Spare Parts Used	Part No.	Qty.
	Collimator- AL002		
	SN: 001/0112		
Service Engineer Signature Date		Authorized Person Signature Date	
Signature Date		Customer / User Signature Date	