

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



log no - 1488, 2609

شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 58280

Customer	Alor Hospital		
Equipment	OHMEDA Incubator		
Model No.	Giraffe incubator		
Serial No.	HDHKS1677 & HDHNS0636		
Authorized Person	Manufacturer OHMEDA medical.		
Customer Complaint	Location Nursery		
Oxygen sensor replacement	Contract / Order No.		
Services / Check Carried out	☐ Installation ☐ Warranty		
	☐ Repair ☐ On Charge		
	☐ Maintenance ☐ Contract		
	☐ Upgrade ☐		
☐ Inspection / Cleaning	☐ Optics Checks		
☐ Calibration / Performance	☐ Pneumatic Checks		
☐ Interface / Communication	☐ Hydraulic Checks		
☐ Safety Checks	☐ Operational Error		
☐ Electrical / Electronics	☐ Mechanical Checks		
☐ Accessories Check	☐		
Time Spent			
Remarks			
Service call attended			
Replaced the oxygen sensor with new one for			
two units of incubator.			
checked and confirmed that the two units are			
working properly.			
No.	Spare Parts Used	Part No.	Qty.
Service Engineer		Authorized Person	
Signature		Signature	
Date		Date	
Customer / User		Signature	
		Date	



FIELD SERVICE REPORT

DEPT: _____ 23/17627

CUSTOMER Al-Rorfa Hospital		EQUIPMENT Incubator		MODEL NO. OILMEDA		DATE 5 / 2 / 24																																									
JOB NO.		LOCATION NICU		SERIAL NO.		ASSET																																									
PARTS USED <table border="1"><thead><tr><th>QTY.</th><th>PART NUMBER</th><th>SIV</th><th>DESCRIPTION</th></tr></thead><tbody><tr><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td></tr></tbody></table>						QTY.	PART NUMBER	SIV	DESCRIPTION																																					CONTRACT	
						QTY.	PART NUMBER	SIV	DESCRIPTION																																						
COST CENTER 4502																																															
BILL PARTS / LABOR ☐																																															
WARRANTY ☐																																															
CONTRACT ☐																																															
INSTALLATION ☐																																															
OTHERS ☐																																															
ENGINEER Amal		HOURS 1																																													

PROBLEM, DIAGNOSIS AND ACTION

service call started
units are checked
* problem is showing in 2 incubator "Oxygen Probe Failure"
that now need to change the O2 sensor.
need 2 Oxygen sensor bottle following:
1) HDHK S1647
2) HDHN S0630
need to make a report request for the parts.

REMARKS

JOB COMPLETED ☐ Yes ☐ No

AWAITING PARTS ☐ Yes ☐ No

ATC ENGINEER SIGNATURE	USER SIGNATURE	AUTHORIZED SIGNATURE & STAMP