

MEDICAL EQUIPMENT REPAIR REQUEST

No. #6 Date: 18/01/2025

Requested by: Fayez Jy Williams

Department: NICU Location: 3rd Floor

SR. No.	Machine	Model	Complaint
H04N50630	Medical Incubator	Graffe	Humidifier not working

Check within Week ☒ ASAP

Engineer Comments

The Humidifier is not working. There is a Humidity Function Error. need to fix it with new one.

Part #: 6600-0245-850

End Comments

Fayez

Requested by

Ahmad Alawadhi

Checked by

Alawadhi


Approved by

LCS 12908

[illegible]

PROBLEM, DIAGNOSIS AND ACTION

- ④ Service call attended
- ④ Unit checked
- ④ Problem: Humidity Error as the Humidifier is not working. The Humidifier needs to be changed with new one
 - ④ Repair Request is needed

REMARKS		
 		
JOB COMPLETED ☐ Yes ☒ No	AWAITING PARTS ☒ Yes ☐ No	
ATC ENGINEER SIGNATURE 	USER SIGNATURE KRISTINA 16-01-25	AUTHORIZED SIGNATURE & STAMP 



FIELD SERVICE REPORT

LCS 12927

CUSTOMER Alor Hospital		EQUIPMENT Incubator		MODEL NO. giraffe ON MEDIA		DATE 11 / 3 / 2025	
JOB NO.		LOCATION NICU		SERIAL NO. HDHNS0630		ASSET	
PARTS USED						CONTRACT QT-2025-LCS-106	
						COST CENTER 4502	
QTY.	PART NUMBER	SIV	DESCRIPTION			BILL PARTS / LABOR ☐ WARRANTY ☐ CONTRACT ☐ INSTALLATION ☐ OTHERS ☒	
1	6600-0245 -850		kit SUCE HMD 120/230				
1			Fuse. 1A Humidifane				
						ENGINEER HOURS - Asmel - Ahmad - Alhamini 1	

PROBLEM, DIAGNOSIS AND ACTION

* service call attended.

* unit it's checked.

* problem the Humidity not working.

* check the ~~the~~ Fuse for ^{in the.} Relay board. and change it.
↳ Humidity.

* the unit working in a good condition.

REMARKS

JOB COMPLETED

☒ Yes

☐ No

AWAITING PARTS

☐ Yes

☒ No

ATC ENGINEER SIGNATURE

USER SIGNATURE

Fene Jy Williamson

AUTHORIZED SIGNATURE & STAMP



www.atc.com.kw