



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 06-11-24

Requested by ALORF MAXXIMOL

Department LDR Location _____

SR. No.	Machine	Model	Complaint
<u>21000100093</u>	<u>Pt. monitor</u>	<u>Telemed</u>	<u>not working</u>

Check within Week

ASAP

Engineer Comments

End Comments

[Signature]
Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO. 336218



شركة أتكو التكنولوجية

تلفون: ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس: ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب: ٢٣٥٥ الجهر، ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63451

Customer	Alort Hospital	Equipment	Patient monitor
		Model No.	VITAPIA 7000k
		Serial No.	2100100093
Authorized Person		Manufacturer	Trismed
Customer Complaint	MIBP Not working	Location	LDR 4
		Contract / Order No.	
Services / Check Carried out		☐ Installation	☐ Warranty
☐ Inspection / Cleaning	☐ Optics Checks	☒ Repair	☐ On Charge
☐ Calibration / Performance	☐ Pneumatic Checks	☐ Maintenance	☐ Contract
☐ Interface / Communication	☐ Hydraulic Checks	☐ Upgrade	☐ _____
☐ Safety Checks	☐ Operational Error		
☐ Electrical / Electronics	☐ Mechanical Checks		
☐ Accessories Check	☐ _____		
		Time Spent	

Remarks: Service call attended. We inspect the unit and checked the MIBP. We swap the BP can MIBP call from another machine. Still the unit is not working. It seems that the MIBP module is faulty. We will confirm with manufacture and get back as soon as possible with quotation.

No.	Spare Parts Used	Part No.	Qty.

Service Engineer

M. Alcon

ATCO Technology Co.

Signature

Date 05/11/2024

Authorized Person

Signature

Date

Signature: [Signature]
Date: 05-11-24

Customer / User

Signature

Date