



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 28/12/24

Requested by Rakhi v.m

Department Ward Location 5B

SR. No.	Machine	Model	Complaint
80091176	Ech machine	EDAN.	1/2 lead print not coming.

Check within Week

ASAP

Engineer Comments

End Comments

Rakhi
Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO. 336218



شركة أتكو التكنولوجية

تلفون: ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس: ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب: ٢٣٥٥ الجبراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63789

Customer	Aloof Hospital	Equipment	Ech machine
		Model No.	SE 1200 Express
		Serial No.	80091176
Authorized Person		Manufacturer	Edan.
Customer Complaint		Location	
	C2 lead not detecting	Contract / Order No.	

Services / Check Carried out	☐ Installation	☐ Warranty
	☒ Repair	☐ On Charge
☐ Inspection / Cleaning	☐ Optics Checks	☐ Maintenance
☐ Calibration / Performance	☐ Pneumatic Checks	☐ Contract
☐ Interface / Communication	☐ Hydraulic Checks	☐ Upgrade
☐ Safety Checks	☐ Operational Error	☐
☐ Electrical / Electronics	☐ Mechanical Checks	
☐ Accessories Check	☐	
	Time Spent	

Remarks	Service call attended. we inspect the unit and tested the Ech cable with Stimulator. we found that the C2 cable is not detecting. The Ech cable is faulty. need to replace the Ech cable
---------	--

No.	Spare Parts Used	Part No.	Qty.

Service Engineer	Authorized Person	Customer / User
NISCOM		Marlene Harsa
ATCO Technology Co.		
Signature	Signature	Signature
Date 29/12/2024	Date	Date 4-1-25