

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63511

Customer	Alor Hospital Jahra			Equipment	X-Ray Machine		
				Model No.			
				Serial No.			
Authorized Person				Manufacturer	Dmax		
Customer Complaint	Error - APP Box			Location	X-Ray Dept.		
				Contract / Order No.			
Services / Check Carried out				☐ Installation	☐ Warranty		
☐ Inspection / Cleaning	☐ Optics Checks			☒ Repair	☒ On Charge		
☐ Calibration / Performance	☐ Pneumatic Checks			☐ Maintenance	☐ Contract		
☐ Interface / Communication	☐ Hydraulic Checks			☐ Upgrade	☐		
☐ Safety Checks	☐ Operational Error			Time Spent			
☐ Electrical / Electronics	☐ Mechanical Checks						
☐ Accessories Check	☐						
Remarks	Service call attended. Checked the unit and found the detector required a reset process. Reset the HIRIS unit. Restarted the unit and found that the detector and other units are working properly.						
No.	Space	Parts Used	Part No.	Qty.			
Service Engineer	Authorized Person			Customer / User			
Signature	Signature			Signature			
Date	Date			Date			