

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO. 336218



شركة أتكو التكنولوجية

تلفون: ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس: ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب: ٢٣٥٥ الجهره, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٢٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 60266

Customer	Alorj Hospital.	Equipment	Laser machine
		Model No.	SP Dynamics
		Serial No.	19101628
Authorized Person		Manufacturer	Fotona
Customer Complaint		Location	OB/layn
not working while using the Scanner		Contract / Order No.	
Services / Check Carried out		☐ Installation ☐ Warranty	
☐ Inspection / Cleaning		☒ Repair	
☐ Optics Checks		☐ On Charge	
☐ Calibration / Performance		☐ Maintenance	
☐ Pneumatic Checks		☐ Contract	
☐ Interface / Communication		☐ Upgrade	
☐ Hydraulic Checks		☐ _____	
☐ Safety Checks		Time Spent	
☐ Operational Error			
☐ Electrical / Electronics			
☐ Mechanical Checks			
☐ Accessories Check			
☐ _____			

Remarks: Service call attended. we inspect the unit and checked the laser out put using G runner 22.8 and found that the laser is not active. we tried the unit directly without the interface and scanner and its working properly. It seems that the G Runner interface have problem. we are taken the G Runner interface to our workshop for further inspection.

No.	Spare Parts Used	Part No.	Qty.
	G runner interface code:- 96 368	S/N: 21000658	

Service Engineer Niscom ATCO Technology Co. Signature Date 25/05/2024.	Authorized Person Signature Date	Customer / User Signature Date
--	--	--------------------------------------