



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: July 3. 2025

Requested by Alma Saman

Department Radiology Location Fluorocopy

x ray - room

SR. No.	Machine	Model	Complaint
	Fluorocopy Machine		not working, due to electrical

Check within Week

ASAP

Engineer Comments

End Comments

Alma Saman

Requested by

Checked By

Approved by



SERVICE / INSTALLATION REPORT

No.: 65215

Customer	Alex Hospital Jahra		Equipment	X-Ray Machine	
			Model No.		
			Serial No.		
Authorized Person			Manufacturer	Primax	
Customer Complaint	Power Fail		Location	XRay Dept	
			Contract / Order No.		
Services / Check Carried out			☐ Installation ☐ Warranty		
☐ Inspection / Cleaning			☒ Repair		
☐ Optics Checks			☒ On Charge		
☐ Calibration / Performance			☐ Maintenance		
☐ Pneumatic Checks			☐ Contract		
☐ Interface / Communication			☐ Upgrade		
☐ Hydraulic Checks			☐ _____		
☐ Safety Checks			☐ Operational Error		
☐ Electrical / Electronics			☐ Mechanical Checks		
☐ Accessories Check			☐ _____		
			Time Spent		
Remarks: Service call attended. Checked the unit and found Power Fail happened for the detector. Resolved the stop detector power supply and APP Box. Checked and found that the unit is working in good condition.					
No.	Spare Parts Used		Part No.	Qty.	
	Note:- Unit problem caused by power failure and need to implement standard instructions given to user to shut down the machine during main electric power shutdown.				
Service Engineer		Authorized Person		Customer / User	
Signature: Date: 03/07/2025		Signature: Date: 3/7/2025		Signature: _____ Date: _____	