



SERVICE / INSTALLATION REPORT

No.: 63841

Customer <i>Alorj Hospital</i>	Equipment <i>ENT Workstation</i>
<i>Jahra</i>	Model No. <i>Futurum III</i>
	Serial No. <i>111632045</i>
Authorized Person	Manufacturer <i>Entomed</i>
Customer Complaint <i>Water leaking from the handset</i>	Location <i>ENT, (5TH FLOOR)</i>
	Contract / Order No.

Services / Check Carried out

- | | |
|---|--|
| ☒ Inspection / Cleaning | ☐ Optics Checks |
| ☒ Calibration / Performance | ☐ Pneumatic Checks |
| ☐ Interface / Communication | ☐ Hydraulic Checks |
| ☒ Safety Checks | ☐ Operational Error |
| ☒ Electrical / Electronics | ☐ Mechanical Checks |
| ☒ Accessories Check | ☐ _____ |

- | | |
|---|---|
| ☐ Installation | ☐ Warranty |
| ☐ Repair | ☐ On Charge |
| ☒ Maintenance | ☐ Contract |
| ☐ Upgrade | ☒ <i>EM</i> |

Time Spent

Remarks

*Found water leaking from the handset.
Replaced handset connectors and fixed leaking.
All connectors are tested ok.
System working good.*

No.	Spare Parts Used	Part No.	Qty.

Service Engineer

Tinca & Noreen
ATCO Technology Co.

Signature

Date *15/03/2025*

Authorized Person

د. كريشنا شاميا
مستشفى العرق
22023120704

Signature

Date *18-3/2025*

Customer / User

Signature

Date