

MEDICAL EQUIPMENT REPAIR REQUEST

No. #7

Date: 15/01/2025

Requested by Ferre Jny Williamson

Department NICU Location 3rd Floor

SR. No.	Machine	Model	Complaint
HDHJ 50528	Medical Incubator	Graffe	Bedlock not working

Check within

☐ Week

☒

ASAP

Engineer Comments

Bed was not Locking. It was not steady
as there was a problem with the Lock. It
has been fixed and now it's in good condition.

End Comments

Ferre
Requested by

Ahmad Alawadhi
Checked By

Ferre
Approved by

FIELD SERVICE REPORT

LCS 12904

[illegible]

PROBLEM, DIAGNOSIS AND ACTION

① service call attended

⑩ Unit checked

⊗ Problem: Bed is Not Locking. it is not steady as there is a problem with the Lock → it has been fixed and working now

④ Unit is in good condition

REMARKS

JOB COMPLETED	☒ Yes	☐ No	AWAITING PARTS	☐ Yes	☒ No
---------------	---	-----------------------------	----------------	------------------------------	--

ATC ENGINEER SIGNATURE

A handwritten signature in blue ink, consisting of a large, stylized 'Z' or 'S' shape followed by a circular flourish and a small dot at the end.

USER SIGNATURE





AUTHORIZED SIGNATURE & STAMP

Blairne Hass