

A/C



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 31/1/2024

Requested by _____

Department Int. Med Location _____

SR. No.	Machine	Model	Complaint
<u>2017123368</u>	<u>PFT Machine</u>	<u>COSMED</u> <u>(Pony FX)</u>	<u>Graph not working.</u>

Check within Week ASAP

Engineer Comments

Handpiece sensor are kept on opposite direction change the
Handpiece sensor on correct direction.

End Comments

Unit is working properly

Hani

Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 58478

Customer	Alorid Hospital.		
Equipment	Spirometry machine.		
Model No.	PONY FX		
Serial No.	2017123368		
Authorized Person	Manufacturer COSMED		
Customer Complaint	Location		
Graph not working.	Contract / Order No.		
Services / Check Carried out	☐ Installation ☐ Warranty		
☐ Inspection / Cleaning	☐ Optics Checks	☒ Repair	☐ On Charge
☐ Calibration / Performance	☐ Pneumatic Checks	☐ Maintenance	☐ Contract
☐ Interface / Communication	☐ Hydraulic Checks	☐ Upgrade	☒ EM
☐ Safety Checks	☐ Operational Error	Time Spent	
☐ Electrical / Electronics	☐ Mechanical Checks		
☐ Accessories Check	☐		
Remarks	Service call attended we inspect the unit and found that the handpiece sensor are kept on opposite direction. we kept the the handpiece sensor on correct way and now the unit is working properly.		
No.	Spare Parts Used	Part No.	Qty.
Service Engineer	Authorized Person	Customer / User	
Nisou ATCO Technology Co.			
Signature	Signature	Signature	
Date 01/02/2024	Date	Date	