



MEDICAL EQUIPMENT REPAIR REQUEST

No. # 1 Date: 13/01/2025

Requested by: Fevie Joy Williams
Department: NICU Location: 3rd floor

SR. No.	Machine	Model	Complaint
H0HK51649	Medical Incubator	Giraffe	Air probe failure

Check within ☐ Week ☒ ASAP

Engineer Comments

Unit Air flow not working. Need to check
the auto supply error and change the part.

End Comments

15/01/25 - check but showing check O₂ supply.

Fevie Joy
Requested by

Ahmad Alawadhi
Checked by

Resulen
Approved by

FIELD SERVICE REPORT

LCS 12909

[illegible]

PROBLEM, DIAGNOSIS AND ACTION

- ④ service call attended
- ④ Unit checked
- ④ Problem: Unit Air flow O₂ not working.
need to check auto supply and
change the part
- ④ Repair Request needed

REMARKS		
JOB COMPLETED ☐ Yes ☒ No	AWAITING PARTS ☒ Yes ☐ No	
ATC ENGINEER SIGNATURE	USER SIGNATURE	AUTHORIZED SIGNATURE & STAMP
	KRISTINA 16-01-25	