
(a) Cascaded current loop
Load change
Supply change
Inductor current [A]
4
3
2
1
0
0
5
10
15
Current request
Input inductor
(b) Bounded duty command
Load change
Supply change
Duty ratio
0.8
0.6
0.4
0.2
0
0
5
10
15
Time [ms]