| GA Division | COMPUTER PREVENTIVE | TMF-G0054 |
|---|--|------------------------------|
| IT | MAINTENANCE CHECKLIST | Version 1.00 |
| User Signatur Conducted by Department:_ PC no. : Factory no. :_ | e: | 1013-07-14 |
| ☑ Delet ☑ Antiv ☑ Disab □ Wind | n Dust on CPU ling Temp/Junk Files irus Scan oling Hotspot ows Update(Optional) ove/Uninstall Unwanted Program | |
| Check Check I Check I | Monitor/Screen for Defect ☑ OK □Not OK Charger for Defect ☑ OK □Not OK Keyboard Casing ☑ OK □Not OK Lan Connection ☑ OK □Not OK Dattery life ☑ OK □Not OK | |
| Others: | | |
| | s following tools to perform the Computer Preventive CPM), the tools are screwdriver, brush, blower, eraser, J45. | Related Documents: TMF-G0058 |

^{*}It is permitted to use this form in both electronic and hard copy.
*The user have to check and compare versions, effective date and sub master information before printing.