GA Division

COMPUTER PREVENTIVE
MAINTENANCE CHECKLIST

TMF-G0054

Version 1.00

User Signature: Range 2023-08-14 Conducted by: Marlo (21052 Department: PC no.: IFXC 1077 Factory no.: Midical	Date: 1023- 08-14
 □ Clean Dust on CPU □ Deleting Temp/Junk Files □ Antivirus Scan □ Disabling Hotspot □ Windows Update(Optional) □ Remove/Uninstall Unwanted Program 	
Check Monitor/Screen for Defect ☐ OK ☐ Not OK Check Charger for Defect ☐ OK ☐ Not OK Check Keyboard Casing ☐ OK ☐ Not OK Check Lan Connection ☐ OK ☐ Not OK Check battery life ☐ OK ☐ Not OK	
Others:	

Reminders:

Must bring this following tools to perform the Computer Preventive Maintenance (CPM), the tools are screwdriver, brush, blower, eraser, crimper and RJ45.

Related Documents: TMF-G0058

^{*}It is permitted to use this form in both electronic and hard copy.

^{*}The user have to check and compare versions, effective date and sub master information before printing.