COMPUTER PREVENTIVE MAINTENANCE CHECKLIST

	User Signature:	: <i>4</i>	<i>ļ.</i> -	_	Date:_	1023-07-19
	Conducted by:_	KNAVE	N JADE PARAN			
	Department: 1			-		
	PC no. : 17	XC0181		_		
	Factory no. :	2		_		
	□ Clean	Dust on	CPU			
	☑ Deletir			es		
	☐ Antivir					
	□ Disabli					
	☑ Windo			nal)		
		•		nted Program		
	Check Me					
	Ohaala O		□Not □ Not □			
	Check C	•	or Delect ⟨□Not			
	Check Ke			UK		
	Onookiik	-	Cuomig C □Not	OK		
,	Check La					
		Ø OH	< □Not	OK		
	Check ba					
			< □Not	OK		
	Others:					٦
						Í
	L					_
Reminders:						
	Must bring this	following	tools to p	erform the Computer Pr	reventive	
	Maintenance (CPM), th	ne tools ar	e screwdriver, brush, blo	ower, erase	r,
	crimper and RJ	45.				
				Related I	Documents:	TCF-G116
Document No:	TCF-G112	VER.	2	Toyoflex Cebu Corp	oration	RETENTION PERIOD

Checked by:

Rey Dagatan

Prepared by:

Rushky Estrera

2023-07-15

Efectivity Date:

Approved by:

Amadito Ortizano

10 YEARS